

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HL ASSURANCE F	PTE LTD		Ref:	CS/HLA22002351/Uqy3	
	11 KEPPEL ROAD #11-01 ABI PLAZA	SINGAPORE 089057	I	Date:	14/03/2022	
			(Code:	HLA	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMQ 6855S	Veh. Inspected		YQ 897T	
	Policy No.	MP315230	Coverage (\$)		0.00	
	Claim No.	MPC02853/JG	Excess (\$)		0.00	
	Assign From	Joel Goh Zan Wei	Assign Date		14/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5. General Information						
	Accident Date	24/09/2021	Inspection Date)		
	Survey held at	LIU'S BROTHER AUTO ENGINE	THER AUTO ENGINEERING WORKSHOP			
		1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						