

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : GBC9583K

Model: MITSUBISHI CANTER FEB

Accident Date : 9/2/2021

(28/5/2014)

Location : BLK 202 JURONG EAST 21 CARPARK

3P: GBD7778Z (Sompot)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front cooling coil <i>Auto</i>	1,845.60	1,845.60 1340	
		Sub-Total:	1,845.60	0.00	0.00
			10%	0%	0%
		After Less %:	1,661.04	0.00	0.00
		Total:		1,661.04	
		After Less 20%:		1,328.83	

1340

Supplementary: 1005

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

