

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1462D

Ref. No : BUS/09/16/5001

 Reg. Date
 : 07/09/2016

 Vehicle Type
 : BUS -12M

Make : MAN
Model : MAN

Name of Driver : Annbalagan Muniandy

Type of Accident : SIDE SWIPE

Date / Time of Accident : 06/09/2016 09:18:00 AM

Accident Reported Date / Time: 06/09/2016 12:00:00 AM

Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No


Towed Back Date/Time :

Replacement Vehicle issued? : No

Accident Repair Job Card No : Special Instruction to ARC, if any :

SMB1462D - LEFT FRONT SCRATCHES SKM8733S (TP) - FRONT RIGHT DENTED

Prepared Date : 07/09/2016 02:49:26 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No:

Mileage

0

Work Shop :

Repair Completed Date / Time:

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

2

Total Labout Charges

530.00

265.00

Total Spray Painting Charges

446.00

Total Material Charges

300.00 0.00

Other Charges

0.00

0.00

TOTAL

0.00

565.00

Lum Sum Total

0.00

976.00

0.00

No. of Repair Days

2.00

1.00

Prepared / Adjusted By

kalvin (LKK)

Arc / Surveyor Sing Off Date

: 11/11/2016 01:29:18 PM

11/11/2016 01:29:18 PM

Prepared / Adjusted Date

Remarks

Prepared Date : 10/11/2016 02:13:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

BUS/09/16/5001 Page:

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | 530.00 | 265.00 |
| Total Labour | 530.00 | 265.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | 446.00 | 300.00 |
| Total Spray Painting & Panel Beating | 446.00 | 300.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable | | | |
|-------------------|--------------------|-------------------------------------|--|--|--|
| Total Other Costs | | | | | |

BUS/09/16/5001

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommen d | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|-----------|-----|--------------------|--------------|---------------------|----------------------|----------------------|--------------------|
| TOTAL MATERIALS | | | | | | | | | | |
| TOTAL MATERIALS(Discounted) | | | | | | | 0.00 | 0.00 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|--------------------|--------------|------------------|-----------|-------------------|-------------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

BUS/09/16/5001