

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP Great American
Hui Zong

ESTIMATE OF REPAIR

Veh# SMH6443U

6B710X234

Model:

HONDA FREED

Accident Date : 11/3/2022

29/1/2019

Location : PIE CHANGI BEFORE THOMSON FLY OVER

3P:

SGT15U (GREAT AMERICAN)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Distorted</i>	943.50	✓	
2	10pcs	Rear bumper clips <i>new</i>		40.00	✓
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	✓
4	2pcs	Rear bumper o/s & n/s reflector <i>new</i>	196.00	x.	
5	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	125.00	✓	
6	2pcs	Rear reverse sensor <i>Damaged</i>	465.60	200 (500)	
7	1pc	Rear end panel <i>Distorted</i>	550.80	✓	
8	1 pc	Rear end panel inner trim <i>Deformed</i>	155.60	✓	
9	2pcs	Rear o/s & n/s tail-lamp <i>crushed</i>	1,440.00	1210	
10	2pcs	Rear o/s & n/s tail-lamp clips <i>new</i>		20.00	✓
11	1pc	Rear tail gate <i>Distorted</i>	1,378.00	1263	
12	1pc	Rear tail gate weatherstrip <i>cut</i>	285.00	✓	
13	1pc	Rear tail gate 'HONDA' emblem <i>new</i>	95.00	✓	
14	1pc	Rear tail gate 'HONDA' emblem wrap <i>new</i>		20.00	x
15	1pc	Rear tail gate 'FREED' emblem <i>3 new</i>	85.00	✓	
16	1pc	Rear tail gate 'HYBRID' emblem	76.60	✓	
17	1pc	Rear tail gate inner trim <i>Distorted</i> <i>crushed</i>	350.60	✓	
18	11pcs	Rear tail gate inner trim clips <i>new</i>		44.00	✓
19	1 pc	Rear tail gate moulding <i>crushed</i>	256.50	✓	
20	1pc	Rear tail gate lock (Upper) <i>Distorted</i>	331.00	✓	
21	1pc	Rear tail gate lock (Lower) <i>new</i>	130.00	x	
22	1pc	Rear wiper motor <i>new</i>	430.40	x.	
23	1 pc	Tailgate handle <i>crushed</i>	66.40	✓	
24	2 pcs	Rear tail gate o/s & n/s reflector <i>cut</i>	940.00	✓	
25	1 pc	Rear windscreen <i>Shattered</i>	1,252.30	✓	
26	1 pc	Rear solar film (3m) <i>new</i>		300.00	200
27	1 pc	Rear windscreen moulding <i>3 new</i>	210.00	✓	
28	1 pc	Rear windscreen sealant		60.00	✓
29	2pcs	Rear o/s & n/s fender inner trim <i>crushed</i>	1,120.20	270	
30	1 pc	Rear reverse sensor <i>Replaced</i>		645.50	x.
31	2pcs	Rear reg. no. plate lamp <i>new</i>		162.40	x
32	1 pc	Rear reg. no. plate <i>3 new</i>		45.00	x
33	1 pc	Rear reg. no. plate bracket		29.00	x
34	1 pc	Front bumper <i>Distorted</i>	986.00	✓	
35	10 pcs	Front bumper clips <i>new</i>		60.00	30
36	1 pc	Front bumper o/s tow cover <i>Missing</i>	67.60	✓	
37	1 pc	Front bumper sponge <i>new</i>	161.20	x	
38	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	218.00	90	

39	1 pc	Front bumper enforcement <i>Best</i>	395.30	✓	
40	1 pc	Front bumper grille (Lower) <i>Del'd</i>	233.40	✓	
41	1 pc	Front grille (upper) <i>could</i>	902.40 690		
42	1 pc	Front grille chrome (upper) <i>could</i>	210.30	✓	
43	8pcs	Front grille clips <i>green</i>		80.00	✓ 20
44	1 pc	Front grille emblem	194.20	✓	
45	1 pc	Front bonnet <i>green</i>	883.60	✓	
46	1 pc	Front bonnet lock	210.40	✓	
47	2pcs	Front o/s & n/s bonnet hinges <i>new</i>	136.40	✓	
48	1 pc	Front support panel <i>Repair</i>	996.80	✓	
49	1 pc	Front support panel top garnish <i>new</i>	166.20	✓	
50	1 pc	Front brace panel <i>Brick</i>	225.40 405	✓	
51	1 pc	Radiator <i>Best</i>	1,622.40 1287	✓	
52	2 pcs	Radiator o/s & n/s bracket <i>new</i>	196.80	70	
53	1 pc	Coolant <i>new</i>		120.00	✓
54	1 pc	Condenser <i>Best</i>	1,044.10	2,985	
55	2 pcs	Front o/s & n/s head lamp <i>Brick</i>	3,229.00	✓	
56	1 pc	Front reg. no. plate <i>Del'd</i>		45.00	✓ 30
57	1 pc	Front reg. no. plate bracket <i>Del'd</i>		29.00	✓
Sub-Total:			22,963.00	1,719.90	0.00
			20%	0%	0%
After Less %:			18,370.40	1719.90	0.00

1783110 S.N: 813
1426488

	Labour	
1	To dismantle damaged parts, straighten & welding.	2,100.00 - 1600 1900
2	To spray painting.	1,700.00 - 1400 1600
3	To remove & refit upholstery to facilitate repair	120.00 80
4	To remove & refit rear windscreen	150.00 120
5	To remove & replace rear reverse sensor.	80.00 50
6	To remove & replace rear tail-gate device.	140.00 80
7	To check for fault code and re-set electrical system	180.00 - X
8	To check wiring.	100.00 60
9	To re-seal anti-rust.	100.00 120 ✓
	To remove condenser and radiator <i>200</i>	
Sub-Total:		4,670.00
Total:		24,760.30
After Less 20%:		19,808.24

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Signature

SAC

24 hr accident call



Supplementary: 1185.60
Total: 20373.08
4/S: 16-31C

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SMH6443U

Model:

HONDA FREED

Accident Date : 11/3/2022

29/1/2019

Location : PIE CHANGI BEFORE THOMSON FLY OVER

3P:

SGT15U (GREAT AMERICAN)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear carpet <i>new</i>	1,200.00	<i>X</i>	
2	1pc	Rear floor panel <i>Repaired Buckled</i>	<i>2,314.00</i>	<i>1219</i>	
3	1pc	Rear floor panel insulator <i>Rec.</i>		210.00	
		Sub-Total:	3,514.00	210.00	0.00
			20%	0%	0%
		After Less %:	2,811.20	210.00	0.00
		Total:		3,021.20	
		After Less 20%:		2,416.96	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Admin

16/03/22

SL

1219

975.20. SW:210

Supplementary: 1185.20

