

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SMH6443U

Model:

HONDA FREED

Accident Date : 11/3/2022

29/1/2019

Location : PIE CHANGI BEFORE THOMSON FLY OVER

3P:

SGT15U (GREAT AMERICAN)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear carpet <i>new</i>	1,200.00	<i>X</i>	
2	1pc	Rear floor panel <i>Repaired Buckled</i>	<i>2,314.00</i>	<i>1219</i>	
3	1pc	Rear floor panel insulator <i>Rec.</i>		210.00	
		Sub-Total:	3,514.00	210.00	0.00
			20%	0%	0%
		After Less %:	2,811.20	210.00	0.00
		Total:		3,021.20	
		After Less 20%:		2,416.96	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Admin

16/03/22

SL

1219

975.20. SW:210

Supplementary: 1185.20

