

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT STRIDES AUTOMOTIVE SERVICES PTE LTD Ref: CS3/SMR22002354/Rty3n2 60 WOODLANDS INDUSTRIAL PARK Date: 22/03/2022 E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. PEQ 6382 SHB 5114S Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. TAX/03/22/2003 Excess (\$) 0.00 **HUA YEN Assign Date** 14/03/2022 Assign From **Vehicle Particulars & Condition** 2. **PROTON WIRA** Make & Model 1298 C.C HIDDEN 2000 Engine No. Year of Reg. PL1C96LNRYB489153 **GREY** Chassis No. Colour 332324 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 175/70 R13 DELIUM 6 mm 175/70 R13 DELIUM L/H Front Tyre 6 mm 175/70 R13 DELIUM R/H Rear Tyre 6 mm **DELIUM** L/H Rear Tyre 175/70 R13 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information** 01/03/2022 15/03/2022 (02:19 PM) Inspect Date / Time Accident Date BLK 1 NO 387J WOODLANDS ROAD YEW TEE IND ESTATE Survey held at Repairer ENG HUP AUTOPARTS ACCESSORIES CO. 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/SMR22002354/Rty3n2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days