

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22002355/KVY3N2**Date:** 07/04/2022**REFERENCE**

Insured/Claimant: Suganthi D/O Vadivelu Policy No: DMPCSNW00160702100

Date of Loss: 11/03/2022

Nature of Claim: OD

Claim No: SNM22D201745/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJL3320A**

Make &amp; Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)

Engine No: 4A910109124

Reg. Date: 24/11/2008 (Man. Year: 2008)

Chassis No: JMYSRCY2A9U000593

Colour: White

Odometer: 180147 km

Engine Capacity: 1499 cc

Market Value/New Car Price: S\$52,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205 55 R16

Rear Tyre Size: 205 55 R16

Front Left Side: Firena 8 mm

Rear Left Side: Firena 2 mm

Front Right Side: Firena 8 mm

Rear Right Side: Firena 2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	380.00	380.00	0.00	0.00
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	117.60	117.60	0.00	0.00
Paintwork Labour	217.00	217.00	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>814.60</b>	<b>814.60</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	57.02	57.02	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>871.62</b>	<b>871.62</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 14/03/2022 Present Location:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 21/03/2022 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #04-01, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2022)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3320A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		380.00 F	*380.00 F
F=Franchise part.						
				Total Parts (\$\$)	380.00	380.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	100.00	100.00
Sub Total (\$\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	217.00	217.00
<u>Labour Items</u>				
2	Total of Labour	New	117.60	117.60
Gross Labour Cost (\$\$)			334.60	334.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >