

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSNW00160702100
 Repairer Reference: 72522
 Date calculated: 14/03/2022 1:38 PM

Full Report
 Registration: SJL 3320A
 Printed: 14/03/2022 1:38 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSNW00160702100	Date of Incident:	11/03/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	MITSUBISHI		
Model:	LANCER (CY,CX,CZ)		
Sub Model:	LANCER		
Model Sheet Number:	32 39 82		
Registration:	SJL 3320A		
VIN number:			
Odometer:	180073		
Model Specs			
FROM 09/2008	AIR CONDITIONING	1.5 LTR 64KW	4-DOOR SALOON
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Not withair
Presumy After Rain
3 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	8.40
514110 00	R + R FRONT BUMPER		8.0	33.60
541011 10)	R + R LEFT HEADLAMP UNIT		1.0	4.20
NO NUMBER	ADJUST HEADLAMPS		2.0	8.40
0741	L/F WING REPAIR		15.0*	63.00
Labour Cost				
Panel / Mechanical Labour		Hrs	WU	
		2.80	28.0	117.60
Total of Labour				117.60

Paint

Paint Work

SYSTEM AZT

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h		
			WU	Price SGD
	L/F WING REPAIR PAINTING >50%		16.0	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

PRINT DATE 14/03/2022

Code	Description
0741	L/F WING REPAIR PAINTING >50%

Price SGD
16.20

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint				
Preparation Main Work Metal		2.50	16.0	
Total	10 WU/h	4.10	41.0	105.00
				172.20

Material Cost - Paint

Repair Painting	Price SGD
Material-constant Metal Preparation	16.20
Total	28.60
	44.80

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0575	LEFT HEADLAMP ASSY	8301A907	Original		
f: OEM Parts					
n: Non-OEM Parts					
u: Used parts					
Savings					
Subtotal					0.00
Fixed Sundry Parts Price					380.00
Total					100.00
					480.00

Final Calculation

Parts	SGD	SGD
Fixed Sundry Parts Price		
Total Parts	380.00	
	100.00	
Labour Time Base 10 WU/h		480.00
Total 28.0 WU X 42.00 SGD/h		
Total of Labour	117.60	
Paint Work Time Base 10 WU/h		117.60
Labour Cost 41.0 WU X 42.00 SGD/h		
Material Cost		
Total Paint Including Material	172.20	
	44.80	
Repair Cost Excludes GST		217.00
GST (+7.0%)		
Repair Cost Included GST		814.60
		57.02
		871.62