



**Industrial Vehicles.
20,000 Served. And Counting.**

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No : 198003963G

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)
Policy No:	DMCVSNA00061082101
Vehicle Reg. No.:	XE2110S
Driver Age/Info:	/ MALE
TP Injury Involved?	NO
Insured/Claimant:	HIAP TAT HOLDING PTE. LTD.
Driver:	PANDIAN ARUNKUMAR

Ref. No:	XE2110S
Date of Loss:	10/03/2022
Driveable?	
Party At Fault:	UNKNOWN
Third Party Involved?	YES

Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)
Vehicle Colour:	WHITE
Engine No:	OM457LA457972C0329537
Odometer:	0 KM

Vehicle Reg. Date: 25/08/2016

Chassis No: FV51SJA20040

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)

COST OF CLAIMS

Parts	14,691.26
Miscellaneous Items	50.00
Labour	6,800.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	21,541.26
+ GST 7.00% (S\$)	1,507.89
Nett Amount (S\$)	23,049.15

This claim is handled by: CHONG KAI LING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 12 Mar 2022)

Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WEATHERSTRIP,FR W/SHLD / CVT	0.00	0.00	*365.22 F
2	1		*GLASS,WINDSHIELD BR	0.00	0.00	*1,652.45 F
3	1		*PANEL,CAB,FR DA X nn	0.00	0.00	*2,715.74 F
4	1		*W/STRIP,FR PANEL CR4 X nn	0.00	0.00	*52.18 F
5	1		*STRAP,PULL DOWN ? X nn	0.00	0.00	*47.54 F
6	1		*SPRING,FR PANEL ? X nn	0.00	0.00	*251.88 F
7	1		*STAY ASSY,RAD GRILLE ? X nn	0.00	0.00	*280.22 F
8	1		*BRACKET,CAB FR CORNER PANEL,LH ? X nn	0.00	0.00	*95.46 F
9	1		*BRACKET,CAB FR CORNER PANEL,RH ? X nn	0.00	0.00	*95.46 F
10	1		*GRILLE,FRONT UPR / BR	0.00	0.00	*288.90 F
11	1		*GRILLE ASSY,FRONT / BR	0.00	0.00	*484.04 F
12	1		*MARK,3-DIA / NC	0.00	0.00	*57.87 F
13	1		*EMBLEM,SUPER GREAT / NC	0.00	0.00	*72.36 F
14	1		*PILLAR ASSY RH X R	0.00	0.00	*1,195.60 F
15	1		*PANEL,WINDSHIELD,UPR DA X nn	0.00	0.00	*606.08 F
16	1		*PANEL,W/SHLD LOWER 96TC DO DA X nn	0.00	0.00	*314.08 F
17	1		*GRIP,FR PANEL -LH X nn	0.00	0.00	*123.50 F
18	1		*GRIP,FR PANEL -RH / BR	0.00	0.00	*123.50 F
19	2		*GASKET,FR PANEL GRIP / NC	0.00	0.00	*6.04 F
20	2		*GASKET,FR PANEL GRIP / NC	0.00	0.00	*12.80 F
21	2		*CAP,FR PANEL GRIP (RH) - mis	0.00	0.00	*14.72 F
22	2		*COVER,FR GRIP (RH) - mis	0.00	0.00	*23.32 F
23	1		*MARK,FUSO / NC	0.00	0.00	*90.09 F
24	1		*ARM ASSY,WINDSHIELD WIPER,CTR - BT	0.00	0.00	*131.08 F
25	1		*ARM ASSY,WINDSHIELD WIPER,LH - BT	0.00	0.00	*131.08 F
26	1		*ARM ASSY,WINDSHIELD WIPER,RH - BT	0.00	0.00	*120.12 F
27	3		*BLADE ASSY,WIPER / CVT	0.00	0.00	*131.40 F
28	1		*MOTOR,WINDSHIELD WIPER ? X nn	0.00	0.00	*466.05 F
29	1		*GRILLE,DEFROSTER,FRONT ? X nn	0.00	0.00	*124.86 F
30	1		*GRILLE,DEFROSTER,FRONT ? X nn	0.00	0.00	*138.90 F
31	1		*PAD,INSTRUMENT PANEL / BR	0.00	0.00	*1,677.75 F
32	1		*BEZEL,CTR ? X nn	0.00	0.00	*213.18 F
33	1		*BEZEL,RH ? X nn	0.00	0.00	*244.26 F
34	1		*BEZEL,LH ? X nn	0.00	0.00	*448.06 F
35	1		*GARNISH,I/PNL,LH ? X nn	0.00	0.00	*324.80 F
36	1		*BUMPER,FR X / AN	0.00	0.00	*1,570.67 F

F=Franchise part.

Total Parts (\$\$)**14,691.26**

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE	35.00
2	1	IU BRACKET	15.00
Sub Total (\$\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REFIX FRONT WINDSCREEN	New	200.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC	New 3500	3,600.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New 150	200.00
4	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	New 600	700.00
5	TO REMOVE AND INSTALL MOBILEYE	New X	400.00
6	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New 1050	1,700.00
Gross Labour Cost (\$\$)			6,800.00

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Stale CLKK)
16/3/22, 10:30 AM

OD- MML
EXAM - ?
L/S
AL Ty
8 dp

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: