

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 12 Mar 2022)**Parts:** N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WEATHERSTRIP,FR W/SHLD <i>CVT</i>	0.00	0.00	*365.22 F
2	1		*GLASS,WINDSHIELD <i>BR</i>	0.00	0.00	*1,652.45 F
3	1		*PANEL,CAB,FR <i>DD</i>	0.00	0.00	*2,715.74 F
4	1		*W/STRIP,FR PANEL <i>CR4</i>	0.00	0.00	*52.18 F
5	1		*STRAP,PULL DOWN <i>?</i>	0.00	0.00	*47.54 F
6	1		*SPRING,FR PANEL <i>?</i>	0.00	0.00	*251.88 F
7	1		*STAY ASSY,RAD GRILLE <i>?</i>	0.00	0.00	*280.22 F
8	1		*BRACKET,CAB FR CORNER PANEL,LH <i>?</i>	0.00	0.00	*95.46 F
9	1		*BRACKET,CAB FR CORNER PANEL,RH <i>?</i>	0.00	0.00	*95.46 F
10	1		*GRILLE,FRONT UPR <i>BR</i>	0.00	0.00	*288.90 F
11	1		*GRILLE ASSY,FRONT <i>BR</i>	0.00	0.00	*484.04 F
12	1		*MARK,3-DIA <i>nc</i>	0.00	0.00	*57.87 F
13	1		*EMBLEM,SUPER GREAT <i>nc</i>	0.00	0.00	*72.36 F
14	1		*PILLAR ASSY RH <i>X R</i>	0.00	0.00	*1,195.60 F
15	1		*PANEL,WINDSHIELD,UPR <i>DD</i>	0.00	0.00	*606.08 F
16	1		*PANEL,W/SHLD LOWER 96TC DO <i>DD</i>	0.00	0.00	*314.08 F
17	1		*GRIP,FR PANEL -LH <i>X</i>	0.00	0.00	*123.50 F
18	1		*GRIP,FR PANEL -RH <i>BR</i>	0.00	0.00	*123.50 F
19	2		*GASKET,FR PANEL GRIP <i>nc</i>	0.00	0.00	*6.04 F
20	2		*GASKET,FR PANEL GRIP <i>nc</i>	0.00	0.00	*12.80 F
21	<i>21</i>		*CAP,FR PANEL GRIP <i>(RH) - mis</i>	0.00	0.00	<i>7.36</i> *14.72 F
22	<i>21</i>		*COVER,FR GRIP <i>(RH) - mis</i>	0.00	0.00	<i>11.66</i> *23.32 F
23	1		*MARK,FUSO <i>nc</i>	0.00	0.00	*90.09 F
24	1		*ARM ASSY,WINDSHIELD WIPER,CTR <i>BT</i>	0.00	0.00	*131.08 F
25	1		*ARM ASSY,WINDSHIELD WIPER,LH <i>BT</i>	0.00	0.00	*131.08 F
26	1		*ARM ASSY,WINDSHIELD WIPER,RH <i>BT</i>	0.00	0.00	*120.12 F
27	3		*BLADE ASSY,WIPER <i>CVT</i>	0.00	0.00	*131.40 F
28	1		*MOTOR,WINDSHIELD WIPER <i>?</i>	0.00	0.00	*466.05 F
29	1		*GRILLE,DEFROSTER,FRONT <i>?</i>	0.00	0.00	*124.86 F
30	1		*GRILLE,DEFROSTER,FRONT <i>?</i>	0.00	0.00	*138.90 F
31	1		*PAD,INSTRUMENT PANEL <i>BR</i>	0.00	0.00	*1,677.75 F
32	1		*BEZEL,CTR <i>?</i>	0.00	0.00	*213.18 F
33	1		*BEZEL,RH <i>?</i>	0.00	0.00	*244.26 F
34	1		*BEZEL,LH <i>?</i>	0.00	0.00	*448.06 F
35	1		*GARNISH,I/PNL,LH <i>?</i>	0.00	0.00	*324.80 F
36	1		*BUMPER,FR <i>X</i>	0.00	0.00	*1,570.67 F

F=Franchise part.

Total Parts (S\$)**14,691.26**

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE <i>X</i>	35.00
2	1	IU BRACKET <i>✓</i> <i>AK</i>	15.00
Sub Total (S\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REFIX FRONT WINDSCREEN	New	200.00 ✓
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC <i>600 X 5</i>	New <i>3500</i>	3,600.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New <i>150</i>	200.00
4	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	New <i>600</i>	700.00
5	TO REMOVE AND INSTALL MOBILEYE	New <i>X</i>	400.00
6	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC <i>350 X 3</i>	New <i>1050</i>	1,700.00
Gross Labour Cost (S\$)			6,800.00

Goldbell Engineering Pte Ltd/XE2110S/12/03/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Stor (LKK)
16/3/22, 10:30 a

OD- MML
EXCH - ?
L/S
AL Ty
8 dp

Parts : \$ 5363.72

SN : \$ 15.00

Labour : \$ 5000.00

\$ 10878.72

Supplementary: \$ 24000.00

\$ 34878.72

Supplementary 2: \$ 11667.59

Total : \$ 46546.31 - 20% = \$ 37230.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Mar 2022)
Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Goldbell Engineering Pte Ltd/XE2110S/18/03/2022 14:05
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CABIN HEAD / DD (photo)	0.00	0.00	24 K / *28,000.00 F
Total Parts (S\$)						28,000.00

F=Franchise part.

Goldbell Engineering Pte Ltd/XE2110S/18/03/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Apr 2022)
Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Goldbell Engineering Pte Ltd/XE2110S/06/04/2022 18:07
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BRACKET ASSY, CAB FR MOUNTING	0.00	0.00	bt 1,500.00 F
2	1		*FRAME ASSY, INST PANEL	0.00	0.00	bt 844.64 F
3	1		*FRAME ASSY, 5DIN	0.00	0.00	bt 112.08 F
4	1		*CONSOLE ASSY, FLOOR	0.00	0.00	cur 1,714.08 F
5	1		*PANEL FLOOR CONSOLE, LH	0.00	0.00	de 176.92 F
6	1		*PANEL, C/LEVER	0.00	0.00	cur 283.94 F
7	1		*LINK, W/SHLD WIPER	0.00	0.00	bt 275.62 F
8	1		*METER COMBINATION	0.00	0.00	cur 3,340.78 F
9	1		*PIPE, A/C COMPRESSOR SUCTION	0.00	0.00	bt 208.66 F
10	1		*COOLING UNIT, A/C	0.00	0.00	cur 1,490.79 F
11	1		*BLOWER ASSY, HEATER	0.00	0.00	cur 409.95 F
12	1		*HEATER ASSY	0.00	0.00	cur 1,310.13 F
Total Parts (S\$)						11,667.59

F=Franchise part.

Goldbell Engineering Pte Ltd/XE2110S/06/04/2022 18:07. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Taufik 7/4/22 Q/pu