

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869  
Tel: +65 6255 2288 | Fax: +65 6265 5388  
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## LONPAC INSURANCE BHD

## Tax Invoice

Inv No. : BPINV22030097  
Invoice Date : 29 Mar 2022  
Ref : BPWJ2203078  
Terms : COD  
Veh. No. : SMN2513X  
Current Mileage: 175076

| #  | Description                                                                                                                   | Qty  | UOM | U/P      | Amt      |
|----|-------------------------------------------------------------------------------------------------------------------------------|------|-----|----------|----------|
| 1  | Front fender panel RH                                                                                                         | 1.00 | PC  | 716.40   | 716.40   |
| 2  | FRONT DOOR RH                                                                                                                 | 1.00 |     | 1,744.60 | 1,744.60 |
| 3  | FRONT DOOR HANDLE RH                                                                                                          | 1.00 |     | 368.40   | 368.40   |
| 4  | WING MIRROR RH                                                                                                                | 1.00 |     | 740.10   | 740.10   |
| 5  | MIRROR                                                                                                                        | 1.00 |     | 444.90   | 444.90   |
| 6  | MOTOR MIRROR                                                                                                                  | 1.00 |     | 225.60   | 225.60   |
| 7  | Front Fender Lamp RH                                                                                                          | 1.00 |     | 54.00    | 54.00    |
| 8  | FRONT BUMPER                                                                                                                  | 1.00 |     | 1,299.00 | 1,299.00 |
| 9  | LESS 10%                                                                                                                      | 1.00 |     | -559.03  | -559.03  |
| 10 | BP-Labour for remove & refix damaged parts front door RH, rear door RH glasses, motor regulator, inner trim board to new door | 1.00 |     | 60.00    | 60.00    |
| 11 | To apply anti-rust                                                                                                            | 1.00 |     | 60.00    | 60.00    |
| 12 | BP-Labour for putty & spray paint all affected areas                                                                          | 1.00 |     | 1,100.00 | 1,100.00 |
| 13 | BP-Labour for check all wiring for proper function                                                                            | 1.00 |     | 20.00    | 20.00    |
| 14 | BP-Labour for panel beating all affected areas                                                                                | 1.00 |     | 600.00   | 600.00   |

### Remarks:

REF: CC4/LPC22002363/KGA3  
DOA: 11.3.2022

ALL PAYMENT SHOULD BE MADE PAYABLE TO MUNICH AUTOCARE PTE LTD  
BANK : UOB BANK  
BANK CODE : 7375  
BRANCH CODE : 001  
ACCOUNT NO. : 4513099651

Subtotal : S\$ 6,873.97  
GST 7.0% : S\$ 481.18  
**Total : S\$ 7,355.15**



For Munich Autocare Pte Ltd

I agree to the price as listed above and affirm that the goods are received in good condition.