

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

Not Authorised
Penny Bepain
5day

ESTIMATION REPORT

Vehicle No : SMN2513X
Make & Model : OPEL, INSIGNIA GRAND SPORT,
W0VZM6EF6K1056975

Estimation No. : E21090019
Date : 14/03/2022

No.	Code	Description	Qty	U/P	Amt
Section: Remark					
1		LONPAC INSURANCE BHD DOA : 11.03.2022 TP (CLAIMS)	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Parts

2		39125440 FRONT FENDER RH	1.00	716.40	716.40	✓
3		39171972 FRONT DOOR RH	1.00	1,744.90	1,744.90	✓
4		13531200 FRONT DOOR HANDLE RH	1.00	368.40	368.40	✓
5		13533640 FRONT DOOR INNER LOCK RH	1.00	508.40	508.40	✓
6		39203329 FRONT DOOR WEATHERSTIP RUBBER RH	1.00	87.60	87.60	✓
7		13583613 FRONT DOOR HINGE UPPER RH	1.00	52.80	52.80	X
8		13583618 FRONT DOOR HINGE LOWER RH	1.00	52.00	52.00	X
9		39185963 FRONT DOOR CHECK RH	1.00	116.40	116.40	X
10		39176501 FRONT DOOR RECULATOR WITH MOTOR RH	1.00	849.60	849.60	✓
11		39186858 FRONT DOOR INNER TRIMBOARD RH	1.00	940.80	940.80	X
12		39171977 REAR DOOR RH	1.00	1,744.80	1,744.80	X
13		13531201 REAR DOOR HANDLE RH	1.00	398.40	398.40	X
14		13533626 REAR DOOR INNER LOCK RH	1.00	207.60	207.60	X
15		39203331 REAR DOOR WEATHERSTIP RUBBER RH	1.00	90.00	90.00	X
16		13590932 REAR DOOR UPPER HINGE RH	1.00	33.60	33.60	X
17		13501716 REAR DOOR LOWER HINGE RH	1.00	27.60	27.60	X
18		39089088 REAR DOOR CHECK RH	1.00	128.40	128.40	X
19		39176508 REAR DOOR RECULATOR WITH MOTOR RH	1.00	1,030.00	1,030.00	X
20		39186839 REAR DOOR INNER TRIM BOARD RH	1.00	1,516.80	1,516.80	X

Continue on next page...

Vehicle No : SMN2513X
 Make & Model : OPEL, INSIGNIA GRAND SPORT,
 W0VZM6EF6K1056975

ESTIMATION REPORT

Estimation No. : E21090019
 Date : 14/03/2022

No.	Code	Description	Qty	U/P	Amt
21		39164899 REAR FENDER RH	1.00	1,053.60	1,053.60 ✓
22		A PILLAR RH	1.00	1,010.00	1,010.00 X
23		39186970 WING MIRROR RH	1.00	740.10	740.10 ✓
24		39075378 MIRROR	1.00	444.90	444.90 ✓
25		13343699 MOTOR MIRROR	1.00	225.60	225.60 ✓
					Amt S\$ 14,088.70
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 14,088.70

Section: Special nett

26		FRONT AND REAR TRIM BOARD CLIPS	10.00	8.00	80.00 X
27			1.00	0.00	0.00
					Amt S\$ 80.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 80.00

Section: Labour

28		LABOUR FOR REMOVE & REFIX DAMAGED PARTS FRONT DOOR RH, REAR DOOR RH GLASSES, MOTOR REGULATOR, INNER TRIM BOARD TO NEW DOOR	1.00	800.00	800.00 600
29		TO APPLY ANTI-RUST	1.00	120.00	120.00 600
30		LABOUR FOR PUTTY & SPRAY PAINT FRONT FENDER RH, FRONT DOOR RH, SIDE MIRROR RH, REAR DOOR RH & REAR FENDER RH AND ROKER PANEL RH POLISH, ETC	1.00	1,600.00	1,600.00 1100
31		TO CHECK ALL WIRING FOR PROPER FUNTION AND DOORS CENTRAL LOCKING SYSTEM FOR PROPER FUNTION	1.00	200.00	200.00 200
32		LABOUR FOR PANEL BEATING ALL AFFECTED AREAS	1.00	1,200.00	1,200.00 600

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Continue on next page...