

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLV9372J

Model: HONDA SHUTTLE

Accident Date : 15/3/2022

23/1/2018

Location : PIE CHANGI BEFORE SERANGOON EXIT

3P: SKV9845Z (AIG)

TP AIG.

Asher.

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Del'd</i>	1,209.20	1050.	
2	10 pcs	Rear bumper clips <i>new</i>		30.00	✓
3	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	182.00	75	
4	2 pcs	Rear bumper o/s & n/s reflector <i>new</i>	162.60	x	
5	2 pcs	Rear bumper o/s & n/s reflector garnish <i>Del'd</i>	190.20	85.10	
6	1 pc	Rear tail-gate <i>Distorted</i>	1,309.00	1195	
7	1 pc	Rear tail-gate inner trim <i>cracked</i>	391.60	2	285
8	16 pcs	Rear tail-gate inner trim clips <i>new</i>	144.00	30	
9	1 pc	Rear tail-gate weather strips <i>new</i>	189.00	✓	
10	1 pc	Rear tail-gate Honda emblem <i>new</i>	76.00	x	
11	1 pc	Rear tail-gate 'hybrid' garnish <i>new</i>	76.50	✓	
12	1 pc	Rear tail-gate shuttle emblem <i>new</i>	66.00	✓	
13	1 pc	Rear tail-gate moulding <i>new</i>	365.00	x	
14	1 pc	Rear tail-gate lock (Upper) <i>Dem'd</i>	220.00	✓	
15	1 pc	Rear tail-gate lock (Lower) <i>new</i>	102.00	x	
16	1 pc	Rear tail-gate handle inner <i>Del'd</i>	54.60	✓	
17	2 pcs	Rear tail-gate o/s & n/s reflector <i>new</i>	856.00	x	
18	2 pcs	Rear tail-gate shock absorber <i>new</i>	468.60	x	
19	2 pcs	Rear tail-gate o/s & n/s hinges <i>new</i>	120.00	x	
20	2 pcs	Rear o/s & n/s fender inner trim <i>cracked</i>	982.80	2	790
21	1 pc	Rear end panel <i>Distorted</i>	589.20	✓	
22	1 pc	Rear end panel inner trim <i>Del'd</i>	212.40	✓	
23	4 pcs	Rear end panel inner trim inner trim clips <i>new</i>		16.00	✓
24	2 pcs	Rear o/s & n/s tail-lamp <i>Del'd</i>	1,162.60	590.	
25	1 pc	Rear o/s tail-lamp panel <i>new</i>	322.00	x	161
26	1 pc	Rear boot floor box <i>Del'd</i>	320.40	2	
27	1 pc	Rear boot floor box cover <i>new</i>	86.50	x	
28	1 pc	Rear boot floor panel <i>new</i>	1,620.00	x	
29	1 pc	Rear boot floor panel insulator <i>new</i>		150	x
30	1 pc	Rear windscreen moulding <i>new</i>		160.00	✓
31	1 pc	Rear windscreen sealant <i>new</i>		88.00	260.
32	1 pc	Rear bumper tow cover <i>Del'd</i>	80.00	45	
33	1 pc	Rear reg. no. plate <i>Del'd</i>		45.00	30
34	1 pc	Rear reg. no. plate bracket <i>Del'd</i>		29.00	✓
35	1 set	Rear reverse sensor <i>Dem'd</i>		288.00	200
Sub-Total:			11,558.20	790.00	0.00
			20%	0%	10%
After Less %:			9,246.56	790.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	1,600.00	800	
2		To spray painting.	1,200.00	800	
3		To remove & refit rear reverse sensor camera.	50.00	✓	
4		To refit and replace rear tail gate <i>ittings</i>	60.00	✓	
5		To remove and refit rear windscreen	450.00	120	
6		To check wiring.	50.00	30	
7		To re-seal anti-rust	69.00	✓	
Sub-Total:			3,179.00		
Total:			13,215.56		
After Less 20%:			10,572.45		

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chan San Chong
Director

DipEng, AAE, MIMI, MSAE (Aust)



bizSAFE AL 8778 1999

Mobil 1



6044.20

4835.36

S.N. 525

Adrian Lij
1/s 15/03/22.

068rup.
Supplementary: 369.60.

Total: 7649.86

A/S: 6.1K.

1620

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SLV9372J

Model:

HONDA SHUTTLE

Accident Date : 15/3/2022

23/1/2018

Location : PIE CHANGI BEFORE SERANGOON EXIT

3P:

SKV9845Z (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear spare wheel board cover <i>not new</i>	310.20	<i>x</i>	
2	2pcs	Rear o/s & n/s bumper sponge <i>crushed</i>	230.20	<i>✓</i> 30.00	
3	1 pc	Rear o/s fender wheel guard <i>torn</i>	182.00	<i>✓</i>	
4	1 pc	Rear end panel inner trim sticket <i>New</i>		80.00 <i>40</i>	
		Sub-Total:	722.40	110.00	0.00
			20%	0%	10%
		After Less %:	577.92	110.00	0.00
		Total:		687.92	
		After Less 20%:		550.34	

Chan

412
329.60 *S.N. 40*

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



Supplementary: 368.60