

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Lee

Date: 16 Mar 2022

## **Preliminary Advice**

Vehicle No	: SGV68G	Accident Date	: 11/03/2022
Make	: MERCEDES-BENZ E250	Policy No.	: DMPCSNW00014152207
Assignment Date	: 15/03/2022	Excess	: S\$3,750.00
Date of Inspection	: 15/3/2022	Est. Duration of Repair	: 8
Inspection At	: JIN AUTO SERVICES PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,342.69
Revised Amount	:S\$	8,347.69
Check Items (Estimated)	:S\$	995.00
Total	:S\$	9,342.69
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	60,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,398.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Lump sum repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .