

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Genevieve Kua

Date: 16 Mar 2022

Preliminary Advice

Vehicle No	: SLQ8135K	Accident Date	: 10/03/2022
Make	: MERCEDES-BENZ E200	Policy No.	: MPC22P00041700
Assignment Date	: 15/03/2022	Excess	: S\$1,250.00
Date of Inspection	: 15/03/2022	Est. Duration of Repair	: 5
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,636.80
Revised Amount	:S\$	5,918.30
Check Items (Estimated)	:S\$	6,684.00
Total	:S\$	12,602.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	22,480.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 32,520.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.