

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

14/3/2022

M/S GREAT AMERICAN INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR NISSAN NV350 - GBH5578B

DOA : 08/03/2022

S/N	QTY	DESCRIPTION		
1	1 PC	FRONT BUMPER	\$	300.00
2	1 PC	FRONT BUMPER REINFORCEMENT	\$	330.00
3	1 PC	FRONT BUMPER RH SIDE RETAINER	\$	85.00
4	1 PC	FRONT RH FOG LAMP	\$	260.00
5	1 PC	FRONT RH FOG LAMP COVER	\$	75.00
6	1 PC	FRONT RH HEADLAMP	\$	230.00
7	1 PC	FRONT RH CORNER PANEL	\$	260.00
8	1 PC	FRONT PANEL	\$	REPAIR
9	1 PC	FRONT RH STEP GARNISH	\$	65.00
10	1 PC	FRONT RH DOOR	\$	REPAIR
11	1 PC	FRONT GRILLE	\$	400.00
			\$	2005.00
		Cost + 15%	\$	300.75
			\$	2305.75
12	1 PC	FRONT RH DOOR CO.STICKER	\$	15.00
13		SPRAY PAINTING	\$	860.00
14		LABOUR CHARGE	\$	780.00
15		WIRING	\$	30.00
		Total	\$	3990.75

