

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

14/3/2022

M/S GREAT AMERICAN INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR NISSAN NV350 - GBH5578B

DOA : 08/03/2022

S/N	QTY	DESCRIPTION			
1	1 PC	FRONT BUMPER	DI	\$	300.00 ✓
2	1 PC	FRONT BUMPER REINFORCEMENT		\$	330.00 ?
3	1 PC	FRONT BUMPER RH SIDE RETAINER	CR	\$	85.00 ✓
4	1 PC	FRONT RH FOG LAMP	CR	\$	260.00 ✓
5	1 PC	FRONT RH FOG LAMP COVER	TO 1 ✓	\$	75.00 ✓
6	1 PC	FRONT RH HEADLAMP	3RD	\$	230.00 ✓
7	1 PC	FRONT RH CORNER PANEL	100	\$	260.00 ✓
8	1 PC	FRONT PANEL	R	\$	REPAIR X
9	1 PC	FRONT RH STEP GARNISH	2L	\$	65.00 ✓
10	1 PC	FRONT RH DOOR	R	\$	REPAIR X
11	1 PC	FRONT GRILLE	CNG	\$	400.00 ✓
				\$	2005.00
				Cost + 15%	\$ 300.75
				\$	2305.75
12	1 PC	FRONT RH DOOR CO.STICKER	1ER	\$	15.00 ✓
13		SPRAY PAINTING		\$	860.00 800
14		LABOUR CHARGE		\$	780.00 550
15		WIRING		\$	30.00 20
				Total	\$ 3990.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
16/3/22
Wm ph. At the 21--
Hdeys L/S