

Vehicle Damage Assessment Report for [SLL9539Z]

Estimate Created: 21/03/2022 02:03 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 02/11/2022 14:14 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Vios
Engine Type			
License Plate Number	SLL9539Z	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provided by LKK: Concluded the cost of repair at part by part \$1,383.00 with 3 days for repair

Insurlogic 3 (02/11/2022 14:13)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Piece, Rear Bumper		10	4.30	0.00 %	43.00
Parts Subtotal					43.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Sundries		1.0	30.00	0.00 %	30.00
Materials Subtotal					30.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
To remove & refix the accident affected area	RnR	720.00	0.00 %	720.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray paint on the accident affected area	Full spray	590.00	0.00 %	590.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 720.00

Paint Labor Subtotal 590.00

Labor Subtotal 1,310.00

Summary

Repair Cost 1,383.00

Discount(0 %) (0.00)

1,383.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 1,383.00