

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 3 Media Close #07-03 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 12/03/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CXRKT Q1	16/03/2017	SLL9539Z	0	13875	75/DS/SLL9539Z
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3802007389		2NRX129795	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SHD2313T ACC DATE: 11/03/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30 100.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				^ X 180.00	
3	B	BP-LAB2 RESET ECU UPON COMPLETION OF REPAIR				^ X 180.00	
4	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				120 2160.00	
5	B	BP-RES2 RESPRAY ACC AFF AREA				1590 1770.00	
6	1	K52159-0U908 COVER, RR BUMPER, L repair	1.00	552.30		XR 552.30	
7	2	K52161-0K040 PIECE, RR BUMPER	10.00	4.30		43.00	
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Will be known" basis - Supplementary item(s) is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			Customer's Signature		Charge Summary		Total 4,985.30 GST 7.00% 348.97 Less 0.00 Amount Due 5,334.27

Customer Copy