9202

ASS	IGN	ME	NT

<u>A551(</u>	<u>GNIVIEN I</u>		
From: Date:	Veh No: SLQ 9184L Yr Regn: 2017 / July		
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No: SLQ 9184L	Make: JEGP CHEROKEE LIMITED 2.4 c.c 2360		
at Workshop m/s Auto (N8 wet	Colour BLAG A/C: Insured / Std / NI / NA		
of GMARSILINA LAWE	Sp.Reading [13674 T/Radio: Insured / Std / NI / NA		
Insured: NTWL	Eng/No:		
Policy No.	C/No: 1C4P JMHB8FW747621		
Claims No.	Gen. Cond: Good (Fair) / Poor / Burnt		
Sum Insured: Excess:	Steering: Morder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or		
Make of Veh:	Modi: Nil (S/Rim / STD A/Rim or		
	Tyre Size: F: 325 SSR 18		
(Policy Condition)	R: 41		
Remark: The veh had commenced its repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / OKO or		
Bal. or Market Value: 98K	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm		
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm		
Est. Repairs: days Res.: Yes or No	D.O.A. (1/03/22 D.O.I. 15/03/22		
புள் Sum: % 3 Val.: Yes or No	Survey held at Auro (NSURE		
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / ØS / N/S / U/C / Rooftop or		
Vehicle: IN / OUT Date: Person Contacted:	Thé U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction REFAIR LIMIT - 31K			
	* 11. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
ate/Time, File Pass to? : Prelli. Report D	Days Of Repair:		
: Final Report R	lesurvey No. of Trip: Survey Fee:		
bate/Time, File Return to?	Transportation:		
Add Fée:	: Site Insp (\$)S+RS,Si		
	: Interview (\$) Photos		
Report Format :	: Tech. Invs (\$) Others		
.ump Sum / I.B.I: (\$			
.ump Sum / I.B.I: (\$)	: Weekend (\$)		



Auto Insure Pte. Ltd.

6 Marsiling Lane Singapore (739145)

E: claims01@autoinsure.com.sg

W: www.autoinsure.com.sg

T: 3157 2626 F: 6368 0081 GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLQ9184L (MARVYN)

Your ref: SMS6091T

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Tour Ter. Sivison

11-Mar-22

ATTENTION: MOTOR CLAIMS DEPT

Email:

Date:

MTCL@income.com.sg

NTUC Income Insurance company

1 Maritime Square Harbourfront Centre #10-01 Singapore 099253

Assessed Vehicle No

: SLQ9184L

Car Make and Model

: VOLKSWAGEN TOURAN 1.6 TDI AT 1T332Z

Date of Accident

: 11-Mar-22

Date of Assessment

: 11-Mar-22

We have carried out a physical assessment of SLQ9184L at our workshop Auto Insure Pte Ltd sustained damages to the RH SIDE portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the RH SIDE portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

P/P

Adjusted Amount

\$

ajustea Amount

3,563.10

Est. Repair Days : 8

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLQ9184L

	MS6091T QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
S/NO	QIT		CONDITION	
		PARTS REPLACEMENT - LIST ITEMS		\$
1	1	FRONT DOOR RH 5+/		4
2	1	FRONT DOOR BADGE RH		\$
3	1	FRONT DOOR LOWER MOULDING RH 900		\$
4	1	FRONT DOOR UPPER HINGE RH		\$
5	1	FRONT DOOR LOWER HINGE RH		\$
6	1	FRONT DOOR LOCK RH		\$
7	1	REAR DOOR RH SW		\$
8	1	REAR DOOR LOWER MOULDING RH MIS		\$
9	1	REAR DOOR LOWER REAR MOULDING RH		\$
10	1	REAR DOOR UPPER HINGE RH		\$
11	1	REAR DOOR LOWER HINGE RH		\$
12	1	REAR DOOR LOCK RH Cut		\$
13	1	REAR DOOR LOCK STRIKER RH		\$
14	1	B PILLAR LOWER PANEL RH	The state of the	\$
15	1	SIDE LOWER PANEL MOULDING RH 500	32 (4) (4) (5) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	\$
16	1	REAR FENDER RH 🗡	+1	\$
17	1	REAR FENDER INNER SHIELD RH		\$ / 10 10 10 10 10 10 10 10 10 10 10 10 10
18	1	REAR WHEEL RIM RH		\$
19	1	REAR SHOCK ABSORBER MOUNTING RH		\$
20	1	REAR SHOCK ABSORBER RH		\$
21	1	REAR KNUCKLE ARM RH		\$
22	1	REAR WHEEL HUB RH	di di	\$
23	1	REAR BRAKE CONTROL UNIT RH	and the second	\$
24	1	REAR UPPER CONTROL ARM RH		\$
25	1	REAR COMPENSATING ARM RH		\$
26	1	REAR LOWER CONTROL ARM RH		\$
27	1	REAR STEERING AXLE RH 7	rafi	\$
28	1	REAR SHOCK ABSORBER RH	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$
1	1		SUB TOTAL	\$
	9		LESS 10%	\$
	El le		TOTAL AMOUNT	\$

Our Ref: SLQ9184L Your Ref: SMS6091T

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	E	ST. BY WORK	SHOP
1	1	REAR BUMPER CLIPS		\$	- M. W.	50.00
2	1	REAR FENDER INNER SHIELD CLIPS 🐺 🏲	w	\$		30.00
3	1	REAR WHEEL TYRE RH		\$	70%	300.00
			SUB TOTAL	\$		380.00
			TOTAL PARTS COST	\$, Ma	380.00

Our Ref: SLQ9184L
Your Ref: SMS6091T

S/NO	DESCRIPTION	A THE STATE OF THE	EST.	BY WORKSHOP
1	LABOUR & PAINTWORK TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS			700 1,200.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS		\$	60 20.00
3	TO CONDUCT DIGNOSIS FAULT CO	DE & RESET	\$	180.00
4	TO REMOVE & REFIT REAR WHEE	L TYRE RH	\$ 5	80.00
5	TO REMOVE & REFIT REAR SUSPENSION RH		\$15	200.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED			800.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		\$	40 60.00
8	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		\$	20 50.00
9	TO VACUUM, WAXING & CLEAN		\$	× 50.00
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS		\$	20 50.00
	The state of the s	TOTAL BEFORE GST	\$	3,330.00
		GST 7%	\$	233.10
		OTAL (PARTS & LABOUR):	\$	3,563.10

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a <u>sum of \$ -</u> for part by part with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hp 90010068
The 90

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/03/2022 13:46 (SGT) Date of Accident 11/03/2022 23:30 (SGT) Exact Location of Accident South Buona Vista Rd, Singapore Additional Location Information ALONG SOUTH BUONA VISTA ROAD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLQ9184L INSURED/POLICYHOLDER

Is company? Name Of Registered Owner S.S KIM ENTERPRISES PTE LTD Company Reg No 2XXXXX920Z Email Address boon@sskim.com.sg Mobile Phone No (Phone) +65-96939028 Alternative Phone No (Office) +65-68978378

VEHICLE PARTICULARS

Manufacturer Jeep Model - commence of the contract of Cherokee Variant LIMITED 2.4 A/T ABS AIRBAG 4WD Exact purpose for which vehicle was being used at time of

Private use

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number

Allianz Insurance Singapore Pte. Ltd. Comprehensive

Private car

Auto

2360

SP2001228397-01 AIS/2021/0003157

No - Claiming third party


DRIVER

CC

Name of Driver NRIC No

SOH BOON KIM SXXXX096F

Date Of Birth	03/05/1988	
Occupation	Indoor	
Date Of Driving Pass	14/10/2014	
Driving experience	7 YEARS AND 5 MONTHS	
Gender	Male	
Mobile Number	(Phone) +65-96939028	
Alt. Phone Number	(Filone) 100 00000	
Email Address	-	
Address	boon@sskim.com.sg 250P PASIR PANJANG ROAD #02-01	
Address complement	250P PASIR PANDANG NO.	
Postcode	-	
Is the driver the policyholder?	117452	
If No, Relationship of the Driver with the Insured	No	
Does Driver Own Other Vehicles?	Employee	
	No	
Vehicle Registration Number of Other Vehicle Owned by Driver		
Insurance Company of Other Vehicle Owned by Driver		
GENERAL INFORMATION OF THE ACCIDENT		
	A Committee of the Comm	
Type of Accident	Side Swipe	
Weather Conditions	Clear	
Road Surface	Dry	
OTHER INFORMATION		
Was any foreign vehicle involved in the accident?	No	- k
Number of vehicles involved in the accident	2	
Was anybody injured in the Accident?	Yes	
Was any injured conveyed to hospital by ambulance?	No	
Was any other vehicle or property damaged?		
Number of Passengers (Including Driver)	1	
Has the driver been approached by unknown person(s)		
soliciting/offering accident claims assistance?	No	
DETAILS OF POLICE ACTION		
Mantha maid and support of the malica?		
Was the accident reported to the police?		
Was notice of intended Prosecution given? If yes, against whom?		
ii yes, agailist wildiii?	실패 기가 가는 것이 되었다면서 그렇게 되는 것이 되는 것이다.	
CIRCUMSTANCES OF ACCIDENT		
ON 11/3/2022 AT ABOUT 2330HRS I WAS TRAVELLING ALOR	NG SOUTH BUONA VISTA ROAD. AS I WAS DRIVING ALONG	
VEHICLE B: SMS6091T CAME FROM THE OTHER LANE AT A	A VERY FAST SPEED & COLLIDE TO MY RIGHT SIDE DOOR.	
ATTACHMENT(S)		
Are accident photos available for attachment?		
Are accident photos available for attachment? Was there any video captured by Car Camera?		
Was there any video captured by Car Carnera? Was there any audio recorded?		
was there any additionate the condense	No	
DETAILS OF OTHE	ER VEHICLE PROPERTY 1	
Vehicle Registration Number	SMS6091T	
Vehicle Manufacturer		
Vehicle Model		
Vehicle Variant	gati -	
Vehicle Colour		
Vehicle Category	Private car	
Name of Driver		
Contact Number	[1] - [[1] :	
Address	- (1) - (1) - (1	



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Addition to the field of a considerate process of the consideration of the consideration of the consideration of the consideration of the constant of the cons
Owner ID Type:	Company
Owner ID: Vehicle Details	920Z
Vehicle No.:	SLQ9184L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2022
Vehicle Make:	JEEP
Vehicle Model:	CHEROKEE LIMITED 2.4 A/T ABS AIRBAG 4WD
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	BFW747621
Chassis No.:	1C4PJMHB8FW747621
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$43,593.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$53,031.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount: Intended COE Rebate Details	\$39,773.00
COE Expiry Date:	26 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$26,828.00
Total Rebate Amount:	\$66,601.00

The information contained herein is correct as at 14 Mar 2022