

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG22002382/KPA3Q2  
**Date:** 26/10/2022

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900117243
<b>Claimant Vehicle No :</b>	SHD317X	<b>Insured Vehicle No :</b>	SMM6218C
Date of Loss:	19/01/2022	Nature of Claim:	TP
		Claim No:	7288030878SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD317X</b>		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002972
Reg. Date:	04/03/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282370
Colour:	Metallic White/Red	Odometer:	548018 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,070.27	200.00	7,870.27	97.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	730.00	3,630.00	83.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,430.27</b>	<b>930.00</b>	<b>11,500.27</b>	<b>92.52</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	870.12	65.10	805.02	92.52
<b>Nett Amount (\$\$)</b>	<b>13,300.39</b>	<b>995.10</b>	<b>12,305.29</b>	<b>92.52</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (\$\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$81.13/day) (\$\$)</b>		162.26		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,264.81</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,200.00</b>		

### INSPECTION

Date of Assignment:	14/03/2022	
Date Inspected:	14/03/2022	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
2	1		*DOOR REGULATOR REAR LH	Serviceable	450.60 FL	*- FL
3	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	758.10 FL	*- FL
4	1		*DOOR HINGE UPPER REAR LH	Repair	241.60 FL	*- FL
5	1		*DOOR HINGE LOWER REAR LH	Repair	169.90 FL	*- FL
6	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
7	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL
8	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
9	1		*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
10	1		*TYRE (\$250.00) (80%)	Cut	300.00 FS	*200.00 FS
11	1		*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*- FS
12	1		*DOOR STICKER 65553333	Not Necessary	100.00 FS	*- FS
13	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
14	1		*FENDER CLIP	Not Necessary	70.00 FS	*- FS
15	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,884.75	200.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	814.48	0.00
Total Parts (\$\$)	8,070.27	200.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	0.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,360.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >