

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X

AAD2201-106

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD317X

VF1ABL15AUC282370

RENAULT

LATITUDE

19/01/2022

AIG/SMM6218C

04/03/2016

14 MAR 2022

PART		LIST	
1	DOOR PANEL REAR LH	\$	2,844.66 X
1	DOOR REGULATOR REAR LH	\$	450.60 X
1	DOOR REGULATOR MOTOR REAR LH	\$	758.10 X
1	DOOR HINGE UPPER REAR LH	\$	241.60 X
1	DOOR HINGE LOWER REAR LH	\$	169.90 X
1	ROCKER PANEL OUTER LH	\$	1,184.99 X
1	BUMPER COVER REAR	\$	561.70 X
1	FENDER PANEL REAR LH	\$	1,933.20 X
TOTAL		\$	8,144.75
10%		\$	814.48
		\$	7,330.28

Special Nett

1	DOOR TRIM CLIP	\$	70.00 X
1	TYRE <i>Damaged tyre @ Spare tyre Compartment.</i>	\$	300.00 <i>80% 2005W</i>
1	DOOR MOULDING CLIP	\$	70.00 X
1	DOOR STICKER 65553333	\$	100.00 X
1	REAR BUMPER CLIP	\$	65.00 X
1	FENDER CLIP	\$	70.00 X
1	FENDER LINER CLIP	\$	65.00 X
TOTAL		\$	440.00

TOTAL PARTS \$ 7,770.28**LABOUR**

To rust-proofing and apply undercoat of the affected areas. \$ 230.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

Putty and spray painting of the affected portion.

\$ 1,400.00 *4401*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *2001*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *201*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

To check steering geometry and computer wheel alignment

\$ 220.00 *601*

TOTAL \$ 4,360.00

Over All Total \$ 12,130.28

(LUMPSUM) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: