

Not Notified
Penalty B4pdm
12 days

13862.95

VEHICLE NO: SMF134L
 CHASSIS NO: RU1-1302990

MODEL: HONDA VEZEL

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>		
FRONT BUMPER <i>767.30</i>	\$ <i>R1</i> 810.00	<input checked="" type="checkbox"/>
FRONT BUMPER RETAINER LHS	\$ <i>D11</i> 30.00	<input type="checkbox"/>
FRONT BUMPER RETAINER RHS	\$ <i>D11</i> 30.00	<input type="checkbox"/>
FRONT BUMPER GRILLE	<i>CM</i> \$ 200.00	<input type="checkbox"/>
FRONT BUMPER GRILLE OUTER GARNISH	<i>CRS</i> \$ 230.00	<input type="checkbox"/>
FRONT BUMPER LOWER SPOILER	<i>D11</i> \$ 360.00	<input type="checkbox"/>
FRONT "HONDA" EMBLEM	\$ <i>M11</i> 30.00	<input type="checkbox"/>
FOG LAMP COVER LHS	\$ <i>D11</i> 60.00	<input type="checkbox"/>
FOG LAMP COVER RHS	\$ <i>Rn</i> 60.00	<input checked="" type="checkbox"/>
FOG LAMP LHS	\$ <i>Rn</i> 270.00	<input checked="" type="checkbox"/>
FOG LAMP RHS	\$ <i>Rn</i> 270.00	<input checked="" type="checkbox"/>
HEADLAMP LHS <i>1859.10</i>	<i>M11 Rn</i> \$ 1,930.00	<input type="checkbox"/>
HEADLAMP RHS <i>1859.10</i>	<i>" "</i> \$ 1,930.00	<input type="checkbox"/>
HEADLAMP BRACKET LHS	\$ <i>CM</i> 50.00	<input type="checkbox"/>
HEADLAMP BRACKET RHS	\$ <i>R</i> 50.00	<input checked="" type="checkbox"/>
FRONT BUMPER REINFORCEMENT	\$ <i>R1</i> 290.00	<input type="checkbox"/>
SUPPORT PANEL	\$ <i>R1</i> 440.00	<input type="checkbox"/>
BONNET	\$ <i>R1</i> 800.00	<input type="checkbox"/>
BONNET RUBBER TRIM <i>120</i>	\$ <i>CM</i> 220.00	<input type="checkbox"/>
BONNET INSULATION	\$ <i>CM</i> 160.00	<input type="checkbox"/>
BONNET LOCK ASSY	\$ <i>R1</i> 150.00	<input type="checkbox"/>
BONNET HINGE LHS	\$ <i>D11</i> 70.00	<input type="checkbox"/>
BONNET HINGE RHS	\$ <i>D11</i> 70.00	<input type="checkbox"/>
FRONT WHEEL ARCH MOULDING LHS	\$ <i>Rn</i> 180.00	<input type="checkbox"/>
BONNET CENTRE BRACKET	\$ <i>R1</i> 80.00	<input type="checkbox"/>
CONDENSOR	\$ <i>R1</i> 620.00	<input type="checkbox"/>
RADIATOR <i>1250.70</i>	<i>R1 Rn</i> \$ 1,400.00	<input type="checkbox"/>
RADIATOR CROWNING	<i>CM</i> \$ 160.00	<input checked="" type="checkbox"/>

	\$ 10,950.00
20%	\$ 2,190.00
	\$ 8,760.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

SPECIAL NETT ITEMS

FRONT SENSORS
CARPLATE W/HOLDER
BUMPER CLIPS 1 SET

	<i>N/A</i>	\$	200.00
	<i>mi'l</i>	\$	40.00
	<i>lu</i>	\$	60.00
Total		\$	300.00
TOTAL PARTS		\$	9,060.00

X
||
||

LKK Auto Consulting Service notify
the Repairer of the following:
• To require the repairer to...

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)		
LABOUR				
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$	2,500.00	<i>1200/-</i>
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$	2,500.00	<i>1300/-</i>
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$	100.00	<i>20/-</i>
4	To provide anti-rust treatment on affected areas	\$	100.00	<i>60/-</i>
5	Remove & refit engine	\$	400.00	<i>250/-</i>
6	Top up aircon gas	\$	100.00	✓
Labour Total :		\$	5,700.00	
TOTAL (PARTS & LABOUR):		\$	14,760.00	