

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NZE1617065470

Name : LOW BOON TIN

Make/Model : TOYOTA AXIO

Vehicle No : SH 4880 H

Accident date : 11.03.2022

No	DESCRIPTION	Qty	Amount (\$S)
----	-------------	-----	--------------

List Items

1	Bonnet	1	\$ 890.60 X
2	Bonnet lock	1	\$ 143.20 X
3	Bonnet lock bracket	1	\$ 151.50 X
4	Front grille	1	\$ 465.00 ✓
5	Front grille emblem	1	\$ 736.80 ✓
6	Front LH headlamp	1	\$ 1,075.40 X
7	Front support panel	1	\$ 535.40 ✓
8	Front bumper	1	\$ 114.20 57.10
9	Front bumper side holder @ \$57.10	2	\$ 78.80 X
10	Front bumper LH side garnish	1	\$ 267.70 ✓
11	Front bumper center lower grille	1	\$ 114.50 ✓
12	Front bumper sponge	1	\$ 421.50 *
13	Front bumper reinforcement	1	\$ 790.40 ✓
14	Front LH fender	1	\$ 176.90 X
15	Front LH fender inner shield	1	\$ 1,012.60 X
16	Front LH door	1	\$ 6,974.50
			\$ 1,743.63
			\$ 5,230.88

Special Nett Items

1	Front number plate	1	\$ 50.00 30
2	Front number plate holder	1	\$ 50.00 30
3	Front LH fender inner shield clips (1 set)	1	\$ 60.00 X
4	Front bumper clips (1 set)	1	\$ 60.00 30
			\$ 220.00

Labour Cost

1	Remove & reinstall air con fill in gas	\$ 150.00 X
2	Remove ,replace & repair consistent to the accident	\$ 1,200.00 600
3	Respray painting	\$ 1,100.00 500
		\$ 2,450.00

Grand Total \$ 7,900.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 3515.17

h/s: 2.8K.

04 Days.