

(08/11/13) wef

ASS. REC. BY: *casu*

REF:

CS/INC22002392/Rqy3

328F

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMR 8316M*at Workshop m/s *AUTO INSURE*of *6, MARILYN LN*

Insured:

NTUL

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

116K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 8316M

Yr Regn:

*2020 / JAN*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN TOURAN 1.4TSI c.c 1395

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading:

60613

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

*WVH222ITZKWO72811*Gen. Cond: *Good* / *Fair* / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt orModi: Nil / *S/Rim* / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / *PIR* / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

07/02/22

D.O.I.

18/03/22

Survey held at

*AUTO INSURE*Des. of Damages: Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 65K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) *S + RS* *SI*☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SMR8316M (MARVYN)**

Your Ref: **PC7076E**

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Date: **12-Mar-22**

ATTENTION: MOTOR CLAIMS DEPT

Email : MTCL@income.com.sg

NTUC Income Insurance company

1 Maritime Square
Harbourfront Centre
#10-01 Singapore 099253

Assessed Vehicle No : SMR8316M
Car Make and Model : VOLKSWAGEN TOURAN 1.4 TSI CL 5T13NZ
Date of Accident : 07-Mar-22
Date of Assessment : 12-Mar-22

We have carried out a physical assessment of SMR8316M at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : L/S
Adjusted Amount : \$ **11,033.10**
Est. Repair Days : **4**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SMR8316M**
Your Ref: **PC7076E**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	1	REAR TAILGATE <i>repair</i>		\$ 3,131.18
2	1	REAR TAILGATE LOGO (TOURAN) <i>new</i>		\$ 159.23
3	1	REAR TAILGATE CHROME GARNISH <i>paint</i>		\$ 850.88
4	1	REAR BUMPER <i>repair</i>		\$ 1,864.88
5	1	REAR BUMPER SIDE RETAINER RH <i>X</i>		\$ 82.10
6	1	REAR BUMPER SIDE RETAINER LH <i>X</i>		\$ 82.10
7	1	REAR BUMPER GUIDE RH <i>X</i>		\$ 101.30
8	1	REAR BUMPER GUIDE LH <i>X</i>		\$ 101.30
9	1	REAR BUMPER REINFORCEMENT <i>X</i>		\$ 1,032.98
10	1	REAR BUMPER LOWER COVER <i>X</i>		\$ 1,032.23
11	1	REAR END PANEL <i>X</i>		\$ 1,218.83
			SUB TOTAL	\$ 9,657.01
			LESS 10%	\$ 965.70
			TOTAL AMOUNT	\$ 8,691.31

Our Ref: **SMR8316M**
Your Ref: **PC7076E**

S/NO	QTY
1	
2	

Our Ref: **SMR8316M**

Your Ref: **PC7076E**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS		\$ 50.00
2	1	REAR END PANEL SEALANT		\$ 60.00
			SUB TOTAL	\$ 110.00
			TOTAL PARTS COST	\$ 8,801.31

Our Ref: **SMR8316M**

Your Ref: **PC7076E**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 200 600.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ X 100.00
3	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 400 600.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ X 50.00
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ X 50.00
7	TO VACUUM, WAXING & CLEAN	\$ X 60.00
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ X 50.00
TOTAL BEFORE GST		\$ 10,311.31
GST 7%		\$ 721.79
TOTAL (PARTS & LABOUR):		\$ 11,033.10

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$11,033.10** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hp 9001 0068
3 days
P/P
15/03/22 @ 1645
Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/02/2022 17:40 (SGT)
Date of Accident 07/02/2022 09:30 (SGT)
Exact Location of Accident Pandan Flyover, Singapore
Additional Location Information EXIT TOWARDS AYE TUAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMR8316M
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner LU CHAO
NRIC No SXXXX328F
Email Address LUCHAO_0805@HOTMAIL.COM
Mobile Phone No (Phone) +65-93218806
Alternative Phone No +65-93218806

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Touran
Variant 1.4 TSI CL 5T13NZ
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1395

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00004772201
Cover Note Number -

DRIVER

Name of Driver LU CHAO
NRIC No SXXXX328F

Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

11/07/1987
 Indoor
 25/09/2014
 7 YEARS AND 5 MONTHS
 Male
 (Phone) +65-93218806
 +65-93218806
 LUCHAO_0805@HOTMAIL.COM
 BLK 765 PASIR RIS ST 71 #11-100
 -
 S510765
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN


ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC7076E
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Bus
 Name of Driver -
 Contact Number -
 Address -
 Address complement -

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was stationary stopped at the stop line of Pandan Flyover about to exit into AYE TUNAS while waiting for vehicle to clear before proceeding when suddenly vehicle B (PC7076E) hit me on my rear causing damage to the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 328F

Vehicle Details

Vehicle No.: SMR8316M
Vehicle to be Exported: No
Intended Deregistration Date: 12 Mar 2022
Vehicle Make: VOLKSWAGEN
Vehicle Model: TOURAN 1.4 TSI CL 5T13NZ
Primary Colour: Grey
Manufacturing Year: 2019
Engine No.: CZDA55315
Chassis No.: WVGZZZ1TZKW072811
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$26,033.00
Original Registration Date: 23 Jan 2020
First Registration Date: 23 Jan 2020
Transfer Count: 0
Actual ARF Paid: \$28,447.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Jan 2030
PARF Rebate Amount: \$21,335.00

Intended COE Rebate Details

COE Expiry Date: 22 Jan 2030
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$37,705.00
COE Rebate Amount: \$29,636.00
Total Rebate Amount: \$50,971.00

The information contained herein is correct as at 12 Mar 2022

OK

Volkswagen Touran 1.4A TSI Comfortline Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Member of:



AUTOMOBILE IMPORTER
& EXPORTER ASSOCIATION (SINGAPORE)
新加坡汽車進出口商會



Price	\$117,800		
Depreciation ⓘ	\$13,210 /yr View models with similar depre	Reg Date	28-Feb-2020 (7yrs 11mths 11days COE left)
Mileage	10,000 km (4.9k /yr)	Manufactured ⓘ	2019
Road Tax ⓘ	\$624 /yr	Transmission	Auto
Dereg Value ⓘ	\$45,195 as of today (change)	OMV ⓘ	\$23,827
COE ⓘ	\$32,889	ARF ⓘ	\$25,358
Engine Cap	1,395 cc	Power	110.0 kW (147 bhp)
Curb Weight ⓘ	1,288 kg	No. of Owners ⓘ	1