



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2206958
3 ANSON ROAD #16-00	INV Date	09/11/2022
SPRINGLEAF TOWER	Reference	CC3/CTI22002393/Rpa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SHB 5798T
Insured Veh.	SLT 1375P
Claim No.	SNM22D201768/C02
Policy No.	DMHCSNA00004252100
Accident Date	12/03/2022
Inspection Date	14/03/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC3/CTI22002393/Rpa3q2

Date: 09/11/2022

Code: CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLT 1375P	<b>Veh. Inspected</b>	SHB 5798T
<b>Policy No.</b>	DMHCSNA00004252100	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM22D201768/C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	14/03/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA RIUS HYBRID 1.8 CVT	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JTDKB3FU603579346	<b>Colour</b>	MAROON
<b>Odometer</b>	319550 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	SAILUN	6 mm
<b>L/H Front Tyre</b>	195/65 R15	SAILUN	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	SAILUN	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	SAILUN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	12/03/2022	<b>Inspection Date</b>	14/03/2022
<b>Survey held at</b>	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5798T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	DOOR LOCK REAR ,RH	NOT NECESSARY	544.70	-
1	DOOR REAR WINDOW REGULATOR SUB-ASSY ,RH	NOT NECESSARY	200.70	-
1	HINGE ASSY ,REAR DOOR ,LOWER RH	NOT NECESSARY	73.30	-
1	HINGE ASSY ,REAR DOOR UPPER RH	NOT NECESSARY	83.30	-
1	DOOR REAR MOTOR ASSY ,POWER WINDOW	NOT NECESSARY	768.60	-
1	PANEL SUB-ASSY ,FENDER REAR RH	TO REPAIR SEE LABOUR	824.80	-
1	PANEL SUB-ASSY ,REAR DOOR ,RH	TO REPAIR SEE LABOUR	1,243.90	-
			3,739.30	-
<b>LABOUR</b>				
	PANEL BEATING & BODY WORK .INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,FENDER REAR RH AND PANEL SUB-ASSY ,REAR DOOR ,RH .		845.00	300.00
	SPRAY PAINT.		756.00	400.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
			1,981.00	700.00
<b>GRAND TOTAL</b>			<b>5,720.30</b>	<b>700.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>700.00</b>

Report Ref No. CC3/CTI22002393/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd






51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHB 5798T

## INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHB 5798T**

**RE-INSPECTION**

