



Case Details

Case Reference Number : TAX/03/22/2032

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5798T

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-17729-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 12/03/2022 02:55 PM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	R
Standard	Main			HINGE ASSY, REAR DOOR , UPPER RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give	X11
Standard	Main			HINGE ASSY, REAR DOOR , LOWER RH	1	73.30	73.30	25.00	54.97	Replace	0	0	Not Give	X11
Standard	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	768.60	768.60	10.00	691.74	Replace	0	0	Not Give	X11
Standard	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	200.70	200.70	25.00	150.52	Replace	0	0	Not Give	X11
Standard	Main			DOOR LOCK REAR , RH	1	544.70	544.70	10.00	490.23	Replace	0	0	Not Give	X11
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	R
Total Spare Part Cost									3,001.46	Surveyor Total		0.00		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,401.17	Final Sur Total		0.00		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO REPAIR REAR RHS PORTION	845.00	300	
Total:		845.00	300.00 /	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY RH REAR DOOR	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			756.00	400.00 /	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>XM</i>	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>XM</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>XM</i>	
4	Main	TO TRANSFER DOOR MECHANISM	120.00	0 <i>XM</i>	
Total:			380.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,401.17	0.00
Total Labour Cost	845.00	300.00
Total Spray Painting	756.00	400.00
Other	380.00	0.00
Overall Total	4,382.17	700.00
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,400.00	700.00
Surveyor Approved Amount		700.00
No of Repair Days*	5	3

	Estimator Assesment(\$)	Surveyor Assesment(\$)
		LUMP SUM REPAIR / RESUVEY AFTER PAINT PHOTO .
Surveyor Name		Rasul
Signature		
Survey Date	14/03/2022	
		<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: