

Section A - Accident Details

Registration Number	SHB5798T
Case Reference Number	TAX/03/22/2032
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MAHMOOD BIN MOHAMMED MUKRY
Type of Accident	Open Door Case
Accident Date and Time	12/3/2022 10:55 PM
Accident Reported Date and Time	14/3/2022 10:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114278
Special Instruction to ARC, if any	TP / RIGHT REAR DOOR
Prepared Date and Time	14/3/2022 12:58 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$2,401.17	\$0.00
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$4,382.17	\$700.00
Lump Sum Total	\$4,400.00	\$700.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	14/03/2022 4:36 PM	14/03/2022 3:49 PM
Signature		
Remarks		LUMP SUM REPAIR / RESUVEY AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2203-0342	Invoice Number	
Quotation Date	24.03.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR RHS PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
Total Other Costs	\$380.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair
		6905052250	DOOR LOCK REAR, RH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given
		6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$200.70	0.00	\$0.00	Replace	Not Given
		6877052031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given
		6875020122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
		8572047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given
Total					\$3,739.30		\$0.00		

R
X
X
X
X
R
R
X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	0.00	
	-20%	
	0.00	L/S \$700/-
+	300.00	
+	400.00	
	700.00	