

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
 (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

Claim Details

Case Ref. No. : TP/032022/5289
Date : 22-03-2022
Accident Date : 12-03-2022

Vehicle Details

Make & Model : Mazda MAZDA5 5-DOOR
 WAGON 2.0L SP.6EAT
 SUNROOF
Chassis No : JM6CW1071G0125180
Registration No : SLL5927M

Third Party Vehicle Details

Registration No : GBJ9858G

S/N	Description	Qty	Amount (S\$)
1	REAR TAILGATE / <i>Price</i>	1.00	\$1,700.00
2	REAR TAILGATE GLASS MOULDING / <i>MC</i>	1.00	\$61.00
3	REAR TAILGATE OUTER GARNISH / <i>CRA</i>	1.00	\$485.00
4	REAR TAILGATE EMBLEM /	1.00	\$45.00
5	REAR TAILGATE "MAZDA" EMBLEM /	1.00	\$46.00
6	REAR TAILGATE "5" EMBLEM /	1.00	\$37.00
7	REAR TAILGATE "SKYACTIV TECHNOLOGY" EMBLEM /	1.00	\$80.00
8	REAR TAILGATE RH REFLECTOR = <i>sent</i>	1.00	\$389.00
9	REAR TAILGATE LH REFLECTOR =	1.00	\$389.00
10	REAR TAILGATE INNER TRIMBOARD / <i>BR</i>	1.00	\$432.00
11	REAR TAILGATE LOCK / <i>cut</i>	1.00	\$257.00
12	REAR TAILGATE RUBBER / <i>trim</i>	1.00	\$178.00
13	REAR RH TAILLAMP = <i>CRA</i>	1.00	\$602.00
14	REAR LH TAILLAMP =	1.00	\$602.00
15	REAR BUMPER / <i>RR</i>	1.00	\$962.00
16	REAR BUMPER RH REFLECTOR X	1.00	\$53.00
17	REAR BUMPER LH REFLECTOR X	1.00	\$53.00
18	REAR BUMPER RH SIDE RETAINER X	1.00	\$48.00
19	REAR BUMPER LH SIDE RETAINER X	1.00	\$48.00
20	REAR BUMPER ANTENNA SENSOR ?	1.00	\$168.00
21	REAR BUMPER BUZZIE SENSOR ?	1.00	\$102.00
22	REAR BUMPER CLIPS @ \$4.50 / <i>MC</i>	1.00	\$4.50
23	REAR END PANEL X <i>Repair</i>	1.00	\$576.00
24	REAR END PANEL TOP TRIM / <i>RR</i>	1.00	\$81.00
25	REAR TOOL BOX / <i>cut</i>	1.00	\$1,110.00
26	REAR TOOL BOX TOP COVER / <i>cut</i>	1.00	\$178.00

\$8,686.50

Discount: -20%

(\$1,737.30)

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

27	REAR TAILGATE REVERSE CAMERA	1.00	\$6,949.20
28	REAR BUMPER PARKING SENSOR	1.00	\$380.00
29	REAR WINDSCREEN GUM	1.00	\$280.00
30	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$80.00
31	TO REPAIR DAMAGES	1.00	\$180.00 120
32	TO SPRAY PAINTING	1.00	\$780.00 580
			\$880.00 700

Subtotal w/o GST:

\$9,529.20

5 Days.

Lugan Repair

After repair photos.

Eric Qiao

22/3/22.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.