

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FENDER RH <i>Repair btr</i>	1,624.80 1,480	16%	1,260.80
2	1	REAR FENDER INNER SHIELD RH <i>x nn</i>	121.86	0.00	121.86
Total Parts (\$\$)					<u>1,746.66</u>

1332

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FENDER INNER SHEILD CLIP <i>NE</i>	40.00	0.00	40.00 20
Sub Total (\$\$)					<u>40.00</u>

20

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00 200
Gross Labour Cost (\$\$)					<u>450.00</u>

400

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	0.00	400.00 200
Gross Labour Cost (\$\$)					<u>400.00</u>

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1332
20
400

1752
20%
1401.60

45-1,400

Rahul
H# 90010068
2 1/2 days
2/12 4/5
16/03/22 @ 1535
Resurvey after repair