

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 12/03/2022

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : LEE SIEW CHIAT
: AXA INSURANCE PTE LTD

Certificate No : GA192428

Accident Date : 13/02/2022

Vehicle No : SLN-5002-X

Make & Model : MAZDA MAZDA3 5-DOOR HATCHBACK 1.5L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR DOOR RH / <i>nn</i>	1,358.40	<i>1049 /</i>
1	REAR DOOR STICKER RH (SET) / <i>nk</i>	85.60	<i>/</i>
1	REAR DOOR HINGE RH (UPPER) <i>X nn</i>	45.50	
1	REAR DOOR HINGE RH (LOWER) <i>X nn</i>	45.50	
1	REAR DOOR CHECKER RH <i>X nn</i>	64.20	
1	REAR FENDER RH <i>X R</i>		
	RESTORE		
1	REAR FENDER PROTECTOR STICKER RH / <i>nk</i>	64.20	<i>/</i>
1	REAR BUMPER / <i>CRU</i>	1,124.50	<i>/</i>
10	REAR BUMPER CLIPS / <i>nk</i>	<i>30</i> 50.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part in spraying resurvey
- Parts prices are subject to quotation
- Third party survey is on a "No Prejudice" basis
- No illegal method to be used
- Supplemental survey is to be surveyed and is subject to final approval by Insurance Company

Acknowledged by Repairer
Signature:

PAGE : 1

Date : 12/03/2022

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LEE SIEW CHIAT

: AXA INSURANCE PTE LTD

Certificate No : GA192428

Accident Date : 13/02/2022

Vehicle No : SLN-5002-X

Make & Model : MAZDA MAZDA3 5-DOOR HATCHBACK 1.5L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

1 REAR BUMPER SIDE BRACKET RH - BR

64.30

Sub Total

2902.20

Discount 20% On Parts

(580.44)

Labour & Misc

LABOUR TO FACILIATE REPAIR

800.00

600

TO CHECK AND RECONNECT ALL NECESSARY WIRINGS

35.00

30

TO SPRAY PAINTING ON AFFECTED AREAS

700.00

600

SPRAY RUST PROOF ON AFFECTED AREA

40.00

30

= 3194.80

L/S - 2555.84

= 2550

Date : 12/03/2022

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LEE SIEW CHIAT

: AXA INSURANCE PTE LTD

Certificate No : GA192428

Accident Date : 13/02/2022

Vehicle No : SLN-5002-X

Make & Model : MAZDA MAZDA3 5-DOOR HATCHBACK 1.5L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

1575.00

Star (LKK)
15/3/22, 12:00

W AL
LIS
My AL 17
5 d/s

3,896.76

Remarks:

SUB TOTAL

GST 7.0 % 272.77

TOTAL 4,169.53

Surveyor's name: _____

Principal's name: LEE SIEW CHIAT

Survey Date & Time: _____

PAGE : 3