



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4272G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FULL STAND	BENT	480.00	400.00
1	HANDLE GUARD	SCRATCHED	260.00	260.00
1	BALANCE	NECESSARY	148.00	148.00
1	SIDE MIRROR	SCRATCHED	155.00	155.00
1	SIDE COVER	SCRATCHED	225.00	225.00
1	TANK	SCRATCHED	850.00	850.00
	LESS 10% DISCOUNT		-	-203.80
			2,118.00	1,834.20
	<u>LABOUR</u>			
	WORKMANSHIP.		250.00	100.00
	ALIGNMENT ADJUST.		150.00	50.00
			400.00	150.00
	GRAND TOTAL		2,518.00	1,984.20

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,984.20
--	--	--	-----------------

Report Ref No. CS/INC22002417/Vty3e2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.