



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 5(608581)

Email: motor@wahhong.sg Roc/GST: (199806235M)

Vehicle No. **YN8778S ISUZU**

Page No. 1 - 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Front windscreen / BR		850.00	/
1	Front windscreen seal / MC		50.00	/
1	Front windscreen moulding upper / MC		90.00	/
1	Front windscreen moulding lower / MC		100.00	/
1	Front panel X R		552.00	/
1	Front panel rubber seal X NN		36.00	/
1	Front panel emblem "Isuzu" / MC		108.00	/
1	Front panel sticker "Reward-NN" / MC		26.40	/
1	Front corner top panel Lh / BR		192.00	/
1	Side mirror arm top round cover Lh / MIS		12.00	/
1	Center grille whole assy / BR		450.00	/
7	Center grille clip @7*\$6 / MC		42.00	/
1	Front bumper / DD		444.00	/
1	Front bumper side bracket Lh / BT		102.00	/
1	Headlamp Lh / BR		252.00	/
1	Signal lamp Lh / BR		90.00	/
1	Condense / DD		528.00	/
1	Condense bracket Lh / BT		58.00	/
1	Condense bracket rh / BT		58.00	/
1	Fan cowling with motor / BR		456.00	/
1	Front door lh / M		816.00	/
1	Front Regulator & Motor LH ? / BT		312.00	/
1	Front door lower wheel arch garnish lh / CRT		78.00	/
1	Front door wheel arch garnish inner rubber seal Lh / CR4		60.00	/
1	Front door outer center protector garnish lh / CRT		60.00	/
1	Front door lock lh ? / Sony d		114.00	/
1	Front door inner trim board lh / CR4		222.00	/
1	Front door window glass lh / BR		280.00	/
1	Front door upper hinge lh / BT		82.00	/
1	Front door lower hinge lh / BT		82.00	/
1	Front door checker lh ? / BT		36.00	/
1	Front door signal lamp lh / BR		90.00	/
1	Front door weatherstrip lh / CR4		138.00	/
1	Step up garnish lh / CR4		114.00	/
1	Front door pillar Lh / DD		1,260.00	/
1	Front door pillar lower extension Lh / DD		180.00	/
1	Pillar Wheel arch rubber seal Lh / CR4		48.00	/
1	Pillar inner arch garnish Lh (upper) / CR4		60.00	/

1	Door pillar rubber seal Lh	CR4	102.00	/
1	Headlamp lower rubber protector Lh	MIS	18.00	/
1	Dashboard	CR4	600.00	/
1	Floor panel (Repair refer to labour)	X R	-	
			9,248.40	
Part Items			10%	924.84
Total:				10,173.24

8628.40  
+ 10%  
9491.24

				<b>Page No. 2 - 3</b>	
<b>SPECIAL NETT ITEMS</b>					
1	ERP sticker	MC	10.00	/	
1	Front Windscreen Sealant	MC	40 / 50.00	/	
1	Front Door Pillar sealant LH	MC	20 / 60.00	/	
1	Headlamp Bulb LH	BR	10 / 20.00	/	
1	Signal Lamp Bulb LH	BR	10 / 20.00	/	
1	Front door Signal Lamp LH	BR	10 / 20.00	/	
1	Front door bulb LH	X MC	20.00		
1	Front Panel sealant	X MC	80.00		
Number plate frnt			BT	\$35	
SN Items Total:			280.00		315
Total Parts			10,453.24		

10,488.74

135



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 5(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN8778S ISUZU

Page No. 3-3

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To remove and replace front Windscreen	150.00	170
5	To remove and refit dashboard and related wire harness and related parts	300.00	200
6	To remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	100.00	/
7	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	50
		2500	
	Labour Total :	4160.00	
	TOTAL (PARTS & LABOUR):	14613.24	

$= 12,126.24$   
 supp = 799.70  


---

 12,925.94

Steve (LKK)  
 16/3/22, 12.00p

OP- M LL  
 Ex corp?  
 L/S  
 M LL M  
 10 dys

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: