



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22002421/Avy3e2 Date: 07/09/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJJ 5562R	Veh. Inspected	SLK 1360D
Policy No.		Coverage (\$)	0.00
Claim No.	C10014231/KY	Excess (\$)	0.00
Assign From	Shafawati Md Rabu	Assign Date	15/03/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRC1890GC208541	Colour	GREY
Odometer	77643 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/03/2022	Inspection Date	16/03/2022
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	