

TEL: 6842 9089 FAX: 6841 2869

Vehicle Number: SLK1360D

Vehicle Model : Honda Odyssey 2.4 EXV-S CVT SR

Manufacturing Year : 2016

Chassis : JHMRC1890GC208541

TP Budget Direct

Voron:

S/N.	Item Description	Amount (\$)
1	Rear Boot Dented	\$ 1,395.93
2	Rear Boot Lamp x 2 pcs crukd. LH	\$ 963.61
3	Rear Boot Top Garnish new \$	\$ 276.59
4	Honda Logo new	\$ 30.19
5	Rear Boot Shock Absorber x 2 pcs Not new	\$ 394.29
6	Rear Wiper Motor new	\$ 314.85
7	Rear Number Plate Lamp x 2 pcs New	\$ 90.09
8	Rear Number Plate Lower Chrome Garnish crukd	\$ 228.38
9	Rear Boot Inner Lock Damaged	\$ 238.10
10	Rear Boot Lock Handle new	\$ 155.84
11	Rear Boot Lock Catch Not new	\$ 31.24
12	Rear Boot Trimboard crukd	\$ 283.37
13	Rear Boot Trimboard Clip x 1 set new	\$ 49.14
14	Rear Boot Trimboard Small Garnish (for hand pulling) New	\$ 24.10
15	Rear Boot Top Spoiler Clip x 1 set Not new	\$ 62.01
16	Rear Boot Rubber Lt	\$ 146.60
17	Taillamp x 2 pcs Not new	\$ 1,923.01
18	Rear Bumper Deformed	\$ 709.14
19	Rear Bumper Reflector x 2 pcs cruked.	\$ 106.24
20	Rear Bumper Clip x 1 set New	\$ 49.14
21	Rear Corner Garnish x 2 pcs cruked	\$ 284.20
22	Keyless Antennae cruked	\$ 99.92
23	Buzzer Sensor cruked	\$ 93.72
24	End Panel Repair	\$ 574.94
25	End Panel Top Garnish Detached	\$ 129.29
26	Rear Windscreen Moulding x 1 set New	\$ 262.90
27	Reverse Sensor x 1 set Damged.	\$ 468.59
28	Reverse Camera Not new	\$ 1,218.32
	Total :	\$ 10,603.72
	Less 10% :	\$ 1,060.37
	Amount :	\$ 9,543.35

S/N	Special Nett Item	Amount (\$)
1	Rear Number Plate with Casing <i>Not rec</i>	\$ 60.00
2	Windscreen Sealant <i>rec</i>	\$ 80.00
3	End Panel Sealant <i>Not rec</i>	\$ 80.00
	<i>60</i>	
	Amount :	\$ 220.00

Labour	Amount (\$)
To check rear electrical wiring system	\$ 80.00
To transfer rear boot component parts to new rear boot	\$ 150.00
To transfer rear windscreen from old boot to new boot	\$ 150.00
To remove, replace, and reinstall rear reverse sensors	\$ 80.00
To apply anti-rusting coating on new and affected areas	\$ 200.00
To remove & reinstall rear interior trims, garnishes etc for necessary repair	\$ 180.00
Labour to remove, cut, change & panel beating	\$ 1,200.00
To putty and respray affected areas	\$ 1,200.00
Labour Total :	\$ 3,240.00
Total (Parts & Labour)	\$ 13,003.35

total: 5449.13
L/s: 4.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: