

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002423/EQY3N2**Date:** 30/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00013232102

Claimant Vehicle No : CB8385R **Insured Vehicle No :** PC8852A

Date of Loss: 11/03/2022 Nature of Claim: TP Claim No: SNM22D201719/C02/JENNY

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB8385R**

Make & Model: GOLDEN DRAGON XML6957J14, 6.7 D (A) Engine No: ISBE422521974744

Reg. Date: 24/06/2011 (Man. Year: 2011) Chassis No: LL3BECDH2BA010157

Colour: Multi-colour Odometer: 362497 km

Engine Capacity: 6693 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,300.00	6,410.00	1,890.00	22.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	4,560.00	790.00	14.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,650.00	10,970.00	2,680.00	19.63
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	13,650.00	8,800.00	4,850.00	35.53
+ GST 7.00/7.00% (S\$)	955.50	616.00	339.50	35.53
Nett Amount (S\$)	14,605.50	9,416.00	5,189.50	35.53

INSPECTION

Date of Assignment: 15/03/2022

Date Inspected: 16/03/2022 Inspected At: Connect3 (HQ)
566 Woodlands Road
Singapore 728697

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Mar 2022)	
Parts:	N/A	GOLDEN DRAGON XML6957J14 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB8385R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP ASSY RH	Cut	1,850.00 F	*1,695.00 FL
2	1		*REAR TAILLAMP RH OUTER PANEL	Broken	2,880.00 F	*2,700.00 FL
3	1		*REAR RH LAST COMPARTMENT PANEL	Dented	1,650.00 F	*1,500.00 FL
4	1		*REAR RH LAST COMPARTMENT GRILLE	Not Necessary	550.00 F	*- FL
5	1		*REAR RH LAST COMPARTMENT INNER STRUCTURE	Dented	780.00 F	*700.00 FL
6	1		*REAR RH LAST COMPARTMENT OUTER LOCK	Bent	285.00 F	*200.00 FL
7	1		*REAR RH LAST COMPARTMENT RUBBER MOULDING	Crushed	105.00 F	*105.00 FL
8	5		*SEALANT	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,300.00	7,100.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	690.00
Total Parts (\$\$)	8,300.00	6,410.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR RH LAST PC SIDE GLASS TO ASSIST REPAIR	New	300.00	250.00
2	REMOVE & REFIT REAR WINDSCREEN TO ASSIST REPAIR	New	400.00	300.00
3	REMOVE & REFIT REAR RH INNER TRIMS,SEATS,UPHOLSTERY ETC TO ASSIST REPAIR	New	300.00	250.00
4	CHECK WIRING	New	50.00	30.00
5	APPLY ANTI RUST	New	100.00	30.00
6	SPRAY PAINTING	New	2,400.00	2,200.00
7	LABOUR CHARGES	New	1,800.00	1,500.00
Gross Labour Cost (\$)			5,350.00	4,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >