

SDH2886H. 2019 Jan.

TP China.  
XiaoChun.

Mercedes Benz CLA180 Coupe. 1555cc

WDD 1173422 NT39069.

Front Number Plate	dented	30(SN) ✓
Front Number Plate Holder	NP	30(SN) ✗
Front Number Plate Garnish	phd	53.90 ✓
Front Bumper	Deformed	1526.80 ✓
Front Bumper Clips	in	50(SN) ✓
Front Bumper Side Holder x 2	LH and	98.10
		$98.1 \times 2 = 196.20$
Front Bumper Sponge	2 NP	203.40 ✗
Front Bumper Reinforcement	ME	585.50 ✗
Front Grille	NH ME	692.10 ✗
Front Grille Chrome Molding LH.	NH ME	98.40 ✗
Headlamp LH.	cracked	2632.50 ✓

4311.80 S.N: 80.  
388062

SDH2886H.

Panel Beating

Spry Painting

Wiring.

~~400~~ 300

~~400~~ 250

~~50~~ 30.

580

Total: 4540.62

L/S: 3.61c.

03 Days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: