

Repair Estimate

Thiam Heng Huat Pte Ltd


176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

NOT Notified
61 Day @ 7500h
Resurvey After Paint
6 days

Make/Model: MERCEDES BENZ C180
Engine/Chassis No.: WDD2050402R008166
Date of accident:
Damaged area: O/S

Date: 15/03/2022
Claim Type: TP
VRN: SLW384D



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Front door o/s <i>1909</i>	1	\$ 2,857.00	\$ 2,857.00	✓
2	Front door top hinge o/s	1	\$ 237.00	\$ 237.00	X
3	Front door lower hinge o/s	1	\$ 216.00	\$ 216.00	X
4	Front door inner trim board o/s	1	\$ 983.00	\$ 983.00	X
5	Front door outer handle o/s	1	\$ 296.00	\$ 296.00	X
6	Front door outer handle lock sensor o/s	1	\$ 195.00	\$ 195.00	X
7	Front door lock o/s	1	\$ 485.00	\$ 485.00	X
8	Front door weatherstrip o/s	1	\$ 283.00	\$ 283.00	X
9	Front door window regulator o/s	1	\$ 536.00	\$ 536.00	X
10	Front door window motor o/s	1	\$ 481.00	\$ 481.00	X
11	Front door window outer channel o/s	1	\$ 153.00	\$ 153.00	X
12	Front door window chrome moulding o/s	1	\$ 235.00	\$ 235.00	X
13	Rear door o/s	1	\$ 2,595.00	\$ 2,595.00	X
14	Rear door top hinge o/s	1	\$ 275.00	\$ 275.00	X
15	Rear door lower hinge o/s	1	\$ 263.00	\$ 263.00	X
16	Rear door inner trim board o/s	1	\$ 994.00	\$ 994.00	X
17	Rear door outer handle o/s	1	\$ 296.00	\$ 296.00	X
18	Rear door outer handle lock sensor o/s	1	\$ 195.00	\$ 195.00	X
19	Rear door lock o/s	1	\$ 385.00	\$ 385.00	X
20	Rear door weatherstrip o/s	1	\$ 288.00	\$ 288.00	X
21	Rear door window regulator o/s	1	\$ 576.00	\$ 576.00	X
22	Rear door window motor o/s	1	\$ 496.00	\$ 496.00	X
23	Rear door window outer channel o/s	1	\$ 145.00	\$ 145.00	X
24	Rear door window chrome moulding o/s	1	\$ 219.00	\$ 219.00	X
25	Rear fender o/s	1	\$ 1,629.00	\$ 1,629.00	X
26	Rear fender cowling o/s	1	\$ 237.00	\$ 237.00	X
27	Rear shock absorber o/s	1	\$ 867.00	\$ 867.00	X
28	Rear shock absorber top mount o/s	1	\$ 192.00	\$ 192.00	X
29	Rear upper arm o/s	1	\$ 644.00	\$ 644.00	X
30	Rear lower arm o/s	1	\$ 687.00	\$ 687.00	X
31	Rear stabilizer endlink o/s	1	\$ 315.00	\$ 315.00	X
32	Rear wheel knuckle o/s	1	\$ 589.00	\$ 589.00	X
33	Rear wheel hub o/s	1	\$ 312.00	\$ 312.00	X
34	Rear wheel hub bearing o/s	1	\$ 276.00	\$ 276.00	X
35	Rocker panel o/s	1	\$ 1,784.00	\$ 1,784.00	X
36	Rocker panel skirting o/s	1	\$ 818.00	\$ 818.00	X
37	Rear bumper	1	\$ 1,987.00	\$ 1,987.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

my car

Repair Estimate

38	Rear bumper side retainer	Sm	2	\$ 89.00	\$ 178.00	X
39	Front fender o/s	985	1	\$ 1,229.00	\$ 1,229.00	X
40	Front fender cowling o/s	1m	1	\$ 215.00	\$ 215.00	X
41	Front shock absorber o/s	697	1	\$ 967.00	\$ 967.00	X
42	Front shock absorber top mount o/s	1m	1	\$ 212.00	\$ 212.00	X
43	Front upper arm o/s	7m	1	\$ 844.00	\$ 844.00	X
44	Front lower arm o/s	537	1	\$ 787.00	\$ 787.00	X
45	Front stabilizer endlink o/s	1m	1	\$ 315.00	\$ 315.00	X
46	Front wheel knuckle o/s	783	1	\$ 989.00	\$ 989.00	X
47	Front wheel hub o/s	1m	1	\$ 312.00	\$ 312.00	X
48	Front wheel hub bearing o/s	166	1	\$ 276.00	\$ 276.00	X
				Subtotal	\$ 30,345.00	
				List discount	10.00%	
				Total	\$ 27,310.50	

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips o/s	nn 12	\$ 5.50	\$ 66.00
2	Rear door inner trim board clips o/s	nn 12	\$ 5.50	\$ 66.00
3	Rear fender cowling clips o/s	nn 8	\$ 5.50	\$ 44.00
4	Rear bumper clips	nn 10	\$ 5.50	\$ 55.00
5	Rocker panel sealant o/s	nn 1	\$ 100.00	\$ 100.00
6	Front fender cowling clips o/s	nn 8	\$ 5.50	\$ 44.00
7	Vinyl wrap (Per panel)	nn 75	\$ 400.00	\$ 2,800.00
8	Rear alloy wheel o/s	nn 1	\$ 850.00	\$ 850.00
9	Front alloy wheel o/s	nn 1	\$ 850.00	\$ 850.00
10	Sundries	nn 1	\$ 50.00	\$ 50.00
			Total	\$ 4,925.00

Labour

No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect n/s doors wire harness of electrical components to facilitate repairs, reconnect and check functions of power windows.	0.5	\$ 100.00
3	To remove and refit n/s doors components to replace both n/s doors, check alignment.	1	\$ 200.00
4	To remove and refit rear windscreen glass to facilitate repair.	0.75	\$ <i>nn</i> 150.00
5	To remove and replace n/s front & rear tyre & rim. To perform tyre balancing.	0.5	\$ 100.00
6	To conduct computerized wheel alignment.	0.75	\$ 150.00
7	To remove and refit n/s front & rear undercarriage for replacement of parts.	2	\$ 400.00
8	Supply spray paint material and necessary items to respray affected area / panel.	8	\$ 1,600.00
9	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 4,400.00

Estimate Grand Total \$ **36,635.50**

Acknowledged by Repairer
Signature:
Date:

Insurance Company