

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0186/2022/JT
DATE : 14-Mar-22
WIP : 15480

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LEONG CHEE KIN
ADDRESS : BLK 8 KIM TIAN PLACE
#07-51
SINGAPORE 163008
TELEPHONE : HP +65 96449440
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800056754-02
VEHICLE NO : SDJ 946 X
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 21/5/2018
ENGINE NO : CVK 058935
CHASSIS NO : WAUZZZF43JA147482
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Mar-22
PLACE OF ACCIDENT : YOTEL CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDJ 946 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250 /	
3	TO DISMANTLE AND LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR.	S/N \$ 280.00 X /	
4	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 280.00 ? /	
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00 ? /	
SUB TOTAL LABOUR CHARGES		: \$ 3,790.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDJ 946 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PART REMOVED. <i>500 X 2</i>	\$ 2,100.00	<i>1090 /</i>
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR. <i>3 X X 550</i>	\$ 3,500.00	<i>490 1650 /</i>
8	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	<i>/</i>
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	<i>X</i>
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384.00	<i>/</i>
TOTAL LABOUR CHARGES		: \$ 10,574.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 946 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / <i>OR</i>	1	\$	2,379.00 / 1903.20	
2	FRONT BUMPER FIXING PARTS <i>X nn</i>	1	\$	613.00	
3	FRONT BUMPER SECURING STRIP <i>1 x nn</i>	2	\$	79.00	
4	FRONT BUMPER GRILLE - CENTER <i>X nn</i>	1	\$	219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>1</i>	1	<i>SX nn</i>	254.00	
6	FRONT BUMPER AIR GUIDE - LH <i>1 x nn</i>	1	\$	72.00	
7	RADIATOR GRILLE <i>X nn</i>	1	\$	1,478.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>1 x nn</i>	1	\$	151.00	
9	FRONT BUMPER GUIDE SECTION - LH <i>OR</i>	1	\$	41.00 / 32.24	
10	FRONT BUMPER TOP COVER <i>X nn</i>	1	\$	143.00	
11	CAUTION STICKER <i>X nn</i>	1	\$	16.00	
12	AIR COND STICKER <i>X nn</i>	1	\$	9.00	
13	FRONT PARKING AID SENSOR - INNER / OUTER <i>X nn</i>	1	\$	265.00	
14	FRONT PARKING AID SENSOR SEAL RING <i>OR</i>	4	\$	10.00 / 6.64	
15	FRONT FENDER - LH <i>OR</i>	1	\$	861.00 / 688.80	
16	FRONT FENDER ATTACHMENT PARTS <i>X nn</i>	1	\$	211.00	
17	FRONT FENDER CLOSING ELEMENT - LH <i>OR</i>	1	\$	81.00 / 64.24	
18	FRONT FENDER BRACKET - LH <i>1 BT</i>	1	\$	41.00 / 32.72	
19	FRONT FENDER BRACE - LH <i>1 BT</i>	1	\$	132.00 / 105.20	
20	POP RIVET <i>1 - OR</i>	6	\$	23.00 / 18.24	
SUB TOTAL SPARE PARTS			\$	7,078.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 946 X

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET CENTER - LH <i>1 X nn</i>	1	\$ 55.00	
22	FRONT FENDER BRACKET END - LH <i>1 X nn</i>	1	\$ 36.00	
23	FRONT WHEEL HOUSING LINER - LH <i>1 CR4</i>	1	\$ 260.00	<i>208</i>
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>1 X nn</i>	1	\$ 149.00	
25	FRONT WHEEL SPOILER <i>1 BR</i>	1	\$ 82.00	<i>65.12</i>
26	FRONT WHEEL SPOILER LOWER - LH <i>1 X nn</i>	1	\$ 39.00	
27	FRONT FENDER STONE CHIP GUARD - LH <i>1 X nn</i>	1	\$ 57.00	
28	FRONT FENDER LEDGE LONG COVER - LH <i>1 X nn</i>	1	\$ 35.00	<i>27.52</i>
29	FRONT FENDER LEDGE SHORT COVER - LH <i>1 X nn</i>	1	\$ 26.00	<i>20.16</i>
30	HEADLIGHT - LH <i>1 CR4</i>	1	\$ 8,301.00	<i>6640.80</i>
31	HEADLIGHT POWER MODULE <i>1 X nn</i>	1	\$ 840.00	
32	HEADLIGHT CONTROL UNIT <i>1 X nn</i>	1	\$ 840.00	
33	HEADLIGHT HOSE - LH <i>1 X nn</i>	1	\$ 42.00	
34	SPACER <i>1 X nn</i>	3	\$ 136.00	
35	LIFT CYLINDER - LH <i>1 X nn</i>	1	\$ 231.00	
36	LIFT CYLINDER BRACKET <i>1 X nn</i>	1	\$ 7.00	
37	LIFT CYLINDER CORRUGATED PIPE <i>1 X nn</i>	1	\$ 107.00	
38	OUTSIDE TEMPERATURE SENSOR BRACKET <i>1 X nn</i>	1	\$ 21.00	
39	REFRIGERANT PIPE <i>1 BT</i>	1	\$ 585.00	<i>468</i>
40	REFRIGERANT PIPE BRACKET <i>1 X nn</i>	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 11,858.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 946 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	SUSPENSION SUBFRAME ? x nn	1	\$ 2,096.00	
42	WISHBONE LINK - LH ? / BT	1	\$ 605.00 / 483.60	
43	WISHBONE SUSPENSION GUIDE - LH ? / BT	1	\$ 1,057.00 / 845.60	
44	WISHBONE GUIDE UPPER - LH ? x nn	1	\$ 575.00	
45	WISHBONE GUIDE - LH ? x nn	1	\$ 575.00	
46	FRONT WHEEL BEARING HOUSING - LH ? / Acc	1	\$ BT 1,070.00 / 856	
47	WISHBONE SWIVEL JOINT ? / BT	1	\$ 214.00 / 170.80	
48	WISHBONE WHEEL HUB ? / nec	1	\$ 498.00 / 398	
49	WISHBONE FLANGE DOUBLE BALL BEARING - LH ? / nec	1	\$ 273.00 / 218	
50	SUSPENSION FORKS - LH ? x nn	1	\$ 293.00	
51	COUPLING ROD ? x nn	2	\$ 258.00	
52	ANTI-ROLL BAR ? x nn	1	\$ 478.00	
53	GAS SHOCK ABSORBER ? x nn	1	\$ 332.00	
54	DRIVE SHAFT - LH ? x nn	1	\$ 2,999.00	
55	TRACK ROD ? / BT	1	\$ 109.00 / 87.20	
56	TIE ROD END ? / BT	1	\$ 217.00 / 173.60	
57	NOISE INSULATION ? x nn	1	\$ 640.00	
58	FRONT NO PLATE x nn	S/N	\$ 60.00	
59	LHS FRONT RIM x (To poshm) R	S/N	TBC	
60	LHS FRONT TYRE - 90% TN	S/N	TBC	288 / ✓
61	SUNDRIES ? / nec	\$	500.00	100 / ✓
TOTAL SPARE PARTS			\$ 31,785.00	
TOTAL LABOUR CHARGES			\$ 10,574.00	
GRAND TOTAL			\$ 42,359.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Stew (LKK)
15/3/22, 3:27p

00-M M ✓
EXC
P/P
by PL by
85 dy

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT