

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0189/2022/JT
DATE : 14-Mar-22
WIP : 15560

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SIM JUAT QUEE MICHAEL GABRIEL
ADDRESS : 1 THONG SOON GREEN
SINGAPORE 787307
TELEPHONE : HP +65 96840989
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900253629-02
VEHICLE NO : SFJ 3289 R
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 14/3/2022
ENGINE NO : CVK 087346
CHASSIS NO : WAUZZZF46KA114431
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Mar-22
PLACE OF ACCIDENT : JUNCTION OF ROCHOR ROAD &
VICTORIA ST

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFJ 3289 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <i>251 x 2</i>	S/N \$ 700.00 <i>500</i>	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELETRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00 ?	
4	TO DISMANTLE BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOOR. <i>781 x 2</i>	S/N \$ 560.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>599 x 4</i>	\$ 5,600.00 <i>2000</i>	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. <i>2 7 x 550 (RH) - 1</i>	\$ 7,000.00 <i>3850</i>	
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 16,124.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / <i>OR</i>	1	\$ 2,379.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$ 254.00	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>X</i>	2	\$ 144.00	
7	RADIATOR GRILLE / <i>OR</i>	1	\$ 1,478.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X</i>	2	\$ 302.00	
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 139.00	
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 899.00	
11	FRONT BUMPER REINFORCEMENT BRACKET - LH / RH <i>?</i>	2	\$ 508.00	
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 82.00	
13	FRONT BUMPER TOP COVER / <i>OR</i>	1	\$ 143.00	
14	"CAUTION" STICKER / <i>OR</i>	1	\$ 16.00	
15	AIR COND STICKER / <i>OR</i>	1	\$ 9.00	
16	FRONT BUMPER LOCK CARRIER BRACKET / <i>OR</i>	1	\$ 154.00	
17	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 64.00	
18	POP RIVET <i>?</i>	4	\$ 4.00	
19	HORN - LH / RH <i>?</i>	2	\$ 273.00	
20	HORN SUPPORT - LH / RH <i>?</i>	2	\$ 66.00	
SUB TOTAL SPARE PARTS		:	\$ 7,824.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR ?	2	\$	530.00
22	FRONT PARKING AID SENSOR SEAL RING - MC	4	\$	10.00
23	FRONT BUMPER WIRING SET ?	1	\$	567.00
24	FRONT FENDER - LH / RH - DD	(2)	\$	1,722.00
25	FRONT FENDER ATTACHMENT PARTS X	1	\$	211.00
26	FRONT FENDER CLOSING ELEMENT - LH / RH - MC	2	\$	162.00
27	FRONT FENDER BRACKET - LH / RH ?	2	\$	82.00
28	FRONT FENDER BRACKET CLOSING ELEMENT - LH / RH ?	2	\$	110.00
29	FRONT FENDER POP RIVET - MC	12	\$	46.00
30	FRONT FENDER BRACE - LH / RH ?	2	\$	264.00
31	FRONT WHEEL HOUSING LINER - LH / RH X	2	\$	522.00
32	FRONT WHEEL SPOILER - LH / RH X	2	\$	164.00
33	FRONT FENDER LEDGE COVER LONG - LH / RH ?	2	\$	70.00
34	FRONT FENDER LEDGE COVER SHORT - LH / RH ?	2	\$	52.00
35	BONNET - DD	1	\$	3,425.00
36	BONNET ATTACHMENT PARTS X	1	\$	431.00
37	BONNET HINGE - LH / RH ?	2	\$	680.00
38	BONNET IMPACT PROTECTION - LH / RH / CENTER - MC	3	\$	93.00
39	BONNET STRIKER - LH / RH ?	2	\$	112.00
40	BONNET LOCK ?	2	\$	455.00
SUB TOTAL SPARE PARTS		:	\$	9,708.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES		REMARKS
		QTY	S/NETT	
41	BONNET ABSORBER X	2	\$ 256.00	
42	BONNET BOWDEN CABLE - CENTER ?	1	\$ 64.00	
43	BONNET BOWDEN CABLE OUTER ?	1	\$ 64.00	
44	BONNET RELEASE CABLE COVER ?	1	\$ 11.00	
45	BONNET RELEASE LEVER ?	1	\$ 15.00	
46	BONNET LOCK CABLE ?	1	\$ 82.00	
47	BONNET PLENUM CHAMBER ?	1	\$ 108.00	
48	BONNET SOUND ABSORBER ? X	1	\$ 382.00	
49	HEADLIGHT - LH / RH - RR	(2)	\$ 16,602.00	
50	LIFT CYLINDER - LH / RH ?	2	\$ 462.00	
51	LIFT CYLINDER BRACKET ?	2	\$ 14.00	
52	LIFT CYLINDER CORRUGATED PIPE ?	1	\$ 107.00	
53	LOCK CARRIER ?	1	\$ 1,127.00	
54	LOCK CARRIER BRACKET - LH / RH ?	2	\$ 85.00	
55	A/C CONDENSER ?	1	\$ 683.00	
56	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	
57	CHARGE AIR COOLER ?	1	\$ 654.00	
58	RADIATOR ?	1	\$ 1,010.00	
59	RADIATOR FAN RING ?	1	\$ 291.00	
60	RADIATOR FAN CONTROL UNIT ?	1	\$ 2,483.00	
SUB TOTAL SPARE PARTS		:	\$ 24,521.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - LH / RH ?	2	\$	64.00
62	RADIATOR AIR GUIDE OUTER - LH / RH ?	2	\$	28.00
63	RADIATOR AIR GUIDE - UPPER ?	1	\$	19.00
64	RADIATOR COOLANT ?	6	\$	282.00
65	INTAKE AIR DUCT - RH X	1	\$	25.00
66	INTAKE AIR GUIDE - TOP V	1	\$	61.00
67	INTAKE HOSE V	1	\$	110.00
68	AIR FILTER BOX X	1	\$	418.00
69	AIR MASS METER X	1	\$	627.00
70	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH (2) (Chore)	2	\$	688.00 / (4T)
71	FRONT NO PLATE - RT	S/N	\$	60.00
72	SUNDRIES ?		\$	400.00
TOTAL SPARE PARTS		:	\$	44,835.00
TOTAL LABOUR CHARGES		:	\$	16,124.00
GRAND TOTAL		:	\$	60,959.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
15/3/22, 3:00pm

OD-MAL
EXCESS-?
8 LYS
P/P
M RLY

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/03/2022 12:19 (SGT)
Date of Accident	12/03/2022 15:40 (SGT)
Exact Location of Accident	Rochor Rd & Victoria St, Singapore
Additional Location Information	JUNCTION OF ROCHOR ROAD & VICTORIA ST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFJ3289R

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIM JUAT QUEE MICHAEL GABRIEL
NRIC No	SXXXX751Z
Email Address	MDGJEM@GMAIL.COM
Mobile Phone No	(Phone) +65-87883996
Alternative Phone No	(Home) +65-64573386

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A4
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1984

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900253629-02
Cover Note Number	-

DRIVER

Name of Driver	SIM KOK ZHONG, JOEL
NRIC No	SXXXX867G

Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

20/01/1990
 Indoor
 26/08/2009
 12 YEARS AND 7 MONTHS
 Male
 (Phone) +65-96933660
 -
 JOEL.SIMKZ@GMAIL.COM
 1 THONG SOON GREEN
 -
 787307
 No
 Child
 No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) No
 soliciting/offering accident claims assistance? No

PASSENGER 1

Name CAIYUN LIN
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

BOTH VEHICLES WERE STOPPED ALONG ROCHOR ROAD. AT THE JUNCTION OF ROCHOR ROAD AND VICTORIA ST. WHEN THE TRAFFIC LIGHT TURNED GREEN, BOTH VEHICLES MOVED INITIALLY. VEHICLE GBD 6941 D THEN CAME TO STOP. HOWEVER, OWN VEHICLE (SFJ 3289 R) WAS UNABLE TO STOP BEFORE COLLIDING INTO GBD 6941 D.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD6914D
 Vehicle Manufacturer Toyota
 Vehicle Model Hiace
 Vehicle Variant -

Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Commercial vehicle
JIANG LEIGANG
(Phone) +65-93831105

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to the insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SEJ 3289R

B: GBD 6914D





Describe Circumstances of the Accident


BOTH VEHICLES WERE STOPPED AT THE JUNCTION OF
ROCHE ROAD AND VICTORIA STREET. WHEN THE TRAFFIC LIGHTS TURNED
GREEN, BOTH VEHICLES MOVED INTIMATELY VEHICLE GBD6941D THEN CAME
TO A STOP, HOWEVER OWN VEHICLE (SP8223E0004) WAS UNABLE TO STOP
BEFORE COLLIDING INTO GBD6941D.

Declaration

We declare the foregoing particulars are true in every respect


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Report Centre
Personnel