

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0189/2022/JT
DATE : 14-Mar-22
WIP : 15560

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SIM JUAT QUEE MICHAEL GABRIEL
ADDRESS : 1 THONG SOON GREEN
SINGAPORE 787307
TELEPHONE : HP +65 96840989
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900253629-02
VEHICLE NO : SFJ 3289 R
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 14/3/2022
ENGINE NO : CVK 087346
CHASSIS NO : WAUZZZF46KA114431
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Mar-22
PLACE OF ACCIDENT : JUNCTION OF ROCHOR ROAD &
VICTORIA ST

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFJ 3289 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <i>251 x 2</i>	S/N \$ 700.00 <i>500</i>	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELETRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00 ?	
4	TO DISMANTLE BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOOR. <i>281 x 2</i>	S/N \$ 560.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. <i>500 x 4</i>	\$ 5,600.00 <i>2000</i>	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. <i>2 7 x 550 (RH) - 1</i>	\$ 7,000.00 <i>3850</i>	
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 16,124.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / <i>OK</i>	1	\$	2,379.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	612.00	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$	79.00	
4	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$	219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$	254.00	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>X</i>	2	\$	144.00	
7	RADIATOR GRILLE / <i>OK</i>	1	\$	1,478.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X</i>	2	\$	302.00	
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	139.00	
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	899.00	
11	FRONT BUMPER REINFORCEMENT BRACKET - LH / RH <i>?</i>	2	\$	508.00	
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$	82.00	
13	FRONT BUMPER TOP COVER / <i>OK</i>	1	\$	143.00	
14	"CAUTION" STICKER / <i>OK</i>	1	\$	16.00	
15	AIR COND STICKER / <i>OK</i>	1	\$	9.00	
16	FRONT BUMPER LOCK CARRIER BRACKET / <i>OK</i>	1	\$	154.00	
17	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$	64.00	
18	POP RIVET <i>?</i>	4	\$	4.00	
19	HORN - LH / RH <i>?</i>	2	\$	273.00	
20	HORN SUPPORT - LH / RH <i>?</i>	2	\$	66.00	
SUB TOTAL SPARE PARTS		:	\$	7,824.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT PARKING AID SENSOR ?	2	\$	530.00	
22	FRONT PARKING AID SENSOR SEAL RING - <i>nc</i>	4	\$	10.00	
23	FRONT BUMPER WIRING SET ?	1	\$	567.00	
24	FRONT FENDER - LH / RH <i>nc</i>	(2)	\$	1,722.00	
25	FRONT FENDER ATTACHMENT PARTS X	1	\$	211.00	
26	FRONT FENDER CLOSING ELEMENT - LH / RH <i>nc</i>	2	\$	162.00	
27	FRONT FENDER BRACKET - LH / RH ?	2	\$	82.00	
28	FRONT FENDER BRACKET CLOSING ELEMENT - LH / RH ?	2	\$	110.00	
29	FRONT FENDER POP RIVET - <i>nc</i>	12	\$	46.00	
30	FRONT FENDER BRACE - LH / RH ?	2	\$	264.00	
31	FRONT WHEEL HOUSING LINER - LH / RH X	2	\$	522.00	
32	FRONT WHEEL SPOILER - LH / RH X	2	\$	164.00	
33	FRONT FENDER LEDGE COVER LONG - LH / RH ?	2	\$	70.00	
34	FRONT FENDER LEDGE COVER SHORT - LH / RH ?	2	\$	52.00	
35	BONNET <i>nc</i>	1	\$	3,425.00	
36	BONNET ATTACHMENT PARTS X	1	\$	431.00	
37	BONNET HINGE- LH / RH ?	2	\$	680.00	
38	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>nc</i>	3	\$	93.00	
39	BONNET STRIKER - LH / RH ?	2	\$	112.00	
40	BONNET LOCK ?	2	\$	455.00	
SUB TOTAL SPARE PARTS		:	\$	9,708.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BONNET ABSORBER X	2	\$	256.00	
42	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00	
43	BONNET BOWDEN CABLE OUTER ?	1	\$	64.00	
44	BONNET RELEASE CABLE COVER ?	1	\$	11.00	
45	BONNET RELEASE LEVER ?	1	\$	15.00	
46	BONNET LOCK CABLE ?	1	\$	82.00	
47	BONNET PLENUM CHAMBER ?	1	\$	108.00	
48	BONNET SOUND ABSORBER ? X	1	\$	382.00	
49	HEADLIGHT - LH / RH - NR	2	\$	16,602.00	
50	LIFT CYLINDER - LH / RH ?	2	\$	462.00	
51	LIFT CYLINDER BRACKET ?	2	\$	14.00	
52	LIFT CYLINDER CORRUGATED PIPE ?	1	\$	107.00	
53	LOCK CARRIER ?	1	\$	1,127.00	
54	LOCK CARRIER BRACKET - LH / RH ?	2	\$	85.00	
55	A/C CONDENSER ?	1	\$	683.00	
56	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$	21.00	
57	CHARGE AIR COOLER ?	1	\$	654.00	
58	RADIATOR ?	1	\$	1,010.00	
59	RADIATOR FAN RING ?	1	\$	291.00	
60	RADIATOR FAN CONTROL UNIT ?	1	\$	2,483.00	
SUB TOTAL SPARE PARTS		:	\$	24,521.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFJ 3289 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - LH / RH ?	2	\$	64.00
62	RADIATOR AIR GUIDE OUTER - LH / RH ?	2	\$	28.00
63	RADIATOR AIR GUIDE - UPPER ?	1	\$	19.00
64	RADIATOR COOLANT ?	6	\$	282.00
65	INTAKE AIR DUCT - RH X	1	\$	25.00
66	INTAKE AIR GUIDE - TOP V	1	\$	61.00
67	INTAKE HOSE V	1	\$	110.00
68	AIR FILTER BOX X	1	\$	418.00
69	AIR MASS METER X	1	\$	627.00
70	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH (2) (Phone)	2	\$	688.00 / (4T)
71	FRONT NO PLATE - nt	S/N	\$	60.00
72	SUNDRIES ?		\$	400.00
TOTAL SPARE PARTS			:	\$ 44,835.00
TOTAL LABOUR CHARGES			:	\$ 16,124.00
GRAND TOTAL			:	\$ 60,959.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Stew (LKK)
15/3/22, 3:27p

00-MAL
EXCESS-?
8 Lys
P/P
M BLy

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT