



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205530

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/09/2022
Reference CC6/CTI22002437/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNC 7396E
Insured Veh. XE 7086X
Claim No. SNM22D201667/C02
Policy No. DMCVSNA00006892202
Accident Date 07/03/2022
Inspection Date 21/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22002437/Kpa3q2 Date: 08/09/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 7086X	Veh. Inspected	SNC 7396E
	Policy No.	DMCVSNA00006892202	Coverage (\$)	0.00
	Claim No.	SNM22D201667/C02	Excess (\$)	0.00
	Assign From		Assign Date	21/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104543748	Colour	METALLIC GREY
	Odometer	109631 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	TRIANGLE	9 mm
	L/H Front Tyre	205/55 R16	TRIANGLE	9 mm
	R/H Rear Tyre	205/55 R16	PIRELLI	3 mm
	L/H Rear Tyre	205/55 R16	PIRELLI	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/03/2022	Inspection Date	21/03/2022
	Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 7396E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR RH FENDER	BENT	958.50	958.50
1	REAR RH FENDER INNER TRIM	SERVICEABLE	285.50	-
1	REAR RH FENDER INNER SHIELD	SERVICEABLE	181.50	-
1	REAR RH TAILLAMP	SCRATCHED	481.50	374.50
1	REAR BUMPER	BUCKLED	674.85	492.20
1	REAR BUMPER RH SIDE RETAINER 1	DISTORTED	132.25	120.00
1	REAR BUMPER RH SIDE RETAINER 2	DISTORTED	131.30	131.30
	LESS 25% DISCOUNT		-711.35	-519.13
			2,134.05	1,557.37
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH SPORT RIM (SN)	DENTED	650.00	450.00
			650.00	450.00
	<u>LABOUR</u>			
	REMOVE & REFIT REAR WINDSCREEN GLASS .		120.00	120.00
	WIRING.		100.00	20.00
	TUFFKOTE.		100.00	30.00
	SPRAY PAINTING.		1,000.00	500.00
	LABOUR CHARGES.		1,000.00	600.00
			2,320.00	1,270.00
	GRAND TOTAL		5,104.05	3,277.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CC6/CTI22002437/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNC 7396E

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNC 7396E

RE-INSPECTION

