

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

07/03/2022

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA ALITS - SNC7396E

1pc rear RH fender
1pc rear RH fender inner trim
1pc rear RH fender inner shield
1pc rear RH taillamp *334.50*
1pc rear bumper *492.20*
1pc rear bumper RH side retainer 1 *120*
1pc rear bumper RH side retainer 2

less 25%

1pc rear RH sport rim *P.1*

remove & refit rear windscreen glass
wiring
tuffkote
spray painting
labour charges
Total

China Taipei
21/03/22
monday
at 11am


Not authorized
11 Rm @ 260ph
Money After Palm
5 days

As \$ 958.50 ✓
in \$ 285.50 x
in \$ 181.50 x
Sur \$ 481.50 ✓
Bu \$ 674.85 ✓
DIY \$ 132.25 ✓
DIY \$ 131.30 ✓

\$ 2,845.40
\$ 711.35
\$ 2,134.05

450h
Re s.nett \$ 650.00 ✓

\$ 120.00 ✓
\$ 100.00 *200*
\$ 100.00 *300*
\$ 1,000.00 *5000*
\$ 1,000.00 *6000*
\$ 5,104.05



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: