Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte

Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Derrick Tan Ming Chye Date: 16 Mar 2022

Preliminary Advice

Vehicle No : SMA8457D **Accident Date** : 09/03/2022

: HONDA VEZEL Policy No. Make

D20MFL0000326 01

Assignment Excess : 15/03/2022 : S\$0.00

Date

Date of

: 16/03/2022

Inspection

Est. Duration of : 5

Repair

Inspection At: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 9,749.12 **Revised Amount** :S\$ 4,825.44 Check Items (Estimated) :S\$ 2,590.96 Total :S\$ 7,416.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

:S\$ 72,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 32,160.00 Salvage Value :S\$

Margin for Repair :S\$ 39,840.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.