

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305508842 Via Fax : EMAIL
Date : 12-3-22 Your Insured : XD 94578R
Time of Fax : _____ Date of Acc : 12-3-22

Attn: Motor Claims Department

Lompal

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A9983D

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

Date/Time: 14.03.2022 15:02

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4183407

JC NO305508842

OWNER

AS CITYCAB PTE LTD
OWNER NO. 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

OUNT CARD NO.

REGN NO.:

SHA9983D

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

12.03.2022 16:30

DATE/TIME IN

YR OF MANU.

14.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU182799

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 12.03.2022
ATURE: 3P.12.03.2022

NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: SHA9983D

JU LONPAC

Vehicle No.:

SHA9983D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>12/03/22</u> Time Received: <u>1635</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer: <u>Mdm. Chong</u> Contact No.: <u>9665 6295</u> Vehicle No.: <u>SHA 9983D</u> Make / Model / Colour: <u>Ioniq</u> Email: _____		5. Nature of Service: <input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks: _____ _____

7. Location: <u>998 Toa Payoh North</u>	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____	

10. Odometer Reading: _____ Fuel Level: <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input checked="" type="checkbox"/> E	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input checked="" type="checkbox"/> Not tested	 #: Cracked X: Dented /: Scratched O: Missing Signature of Customer: _____
--	---	--

Job Attended

12. Tow Truck / Recovery Van: <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> OTHERS Name of Driver: <u>Bei</u> Vehicle No.: <u>YP7646A</u> Time Dispatch: <u>1635</u> Time of Arrival: <u>1705</u> Time Completed: <u>1735</u>	
--	--

Cash Invoice Details (if applicable)

13. Cash Invoice No.:	
-----------------------	--

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

<u>12/03/22</u> Date	<u>1705</u> Time	Signature of Customer
-------------------------	---------------------	-----------------------

14. WORKSHOP

Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
-------------------------------	------------------------	------------------------------------

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA9983D

DATE: 14. March 2022

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 12. Mar. 2022

LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MLDG			\$451.25
1	REAR BUMPER BEAM			\$394.80
1	REAR BUMPER BEAM BRACKET LH			\$138.10
1	REAR BUMPER BEAM BRACKET RH			\$138.10
1	REAR BUMPER SIDE BRACKET LH			\$55.80
1	BOOTLID ASSY			\$2,480.00
1	BOOTLID EMBLEM – IONIQ			\$31.30
1	BOOTLID EMBLEM – HYBRID			\$24.30
1	BOOTLID EMBLEM – H			\$28.00
1	REAR FOG LAMP			\$201.50
1	ANTENNA ASSY SMARTKEY			\$40.50
1	BOOTLID LAMP LH			\$794.40
1	BOOTLID LAMP RH			\$794.40
1	TAILLAMP ASSY LH			\$870.40
10	REAR BUMPER CLIPS			\$22.00
1	BOOTLID WINDSCREEN GLASS – SMALL			\$607.20
1	BOOTLID WINDSCREEN GLASS- MOULDING			\$48.50
1	BOOTLID LOWER GARNISH			\$36.10
1	REAR END PANEL			\$532.00
1	REAR END PANEL GARNISH			\$346.80
SUB TOTAL				\$8,494.85
LESS 20%				\$1,698.97
DISCOUNTED TOTAL				\$6,798.88
BOOTLID COMFORT LOGO				\$30.00
BOOTLID COMFORT TEL.NOS LOGO				30 NET
BOOTLID APPS LOGO				40 NET
REVERSE SENSOR				180 NET
REAR BUMPER MAT				50 NET
WINDSCREEN SEALANT				46 NET
Labour Charge				
PANEL BEATING – REAR				\$1,400.00
SPRAY PAINT - REAR				\$800.00
REMOVE/REFIX REVERSE SENSOR				\$50.00
CHECK WIRING				\$50.00
TUFF KOTE				\$50.00
				\$376.00

REMOVE/REFIX REAR WINDSCREEN GLASS
TOWING

\$120.00

\$60.00

TOTAL LABOUR

\$2,530.00

ESTIMATE TOTAL

\$9,701.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.