

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON NISSAN CABSTAR

VEHICLE NO : GB8486D

DATE : 15/03/2022

PARTS DESCRIPTION

LIST ITEMS

- 1 FRONT BUMPER / *cut*
- 2 FRONT BUMPER REINFORCEMENT X *nn*
- 3 FRONT GRILLE / *BR*
- 4 FRONT GRILLE LOGO / *del*
- 5 FRONT PANEL X *repair*
- 6 FRONT PANEL EMBLEM CABSTAR / *del*
- 7 FRONT WIPER PANEL X *nn*
- 8 LH FRONT HEADLAMP / *CRA*
- 9 LH FRONT HEADLAMP BRACKET X *nn*
- 10 LH FRONT HEADLAMP LOWER APRON PANEL X *nn*
- 11 RH FRONT HEADLAMP / *BR*
- 12 RH FRONT HEADLAMP BRACKET X
- 13 RH FRONT HEADLAMP LOWER APRON PANEL X *nn*
- 14 LH FRONT MIRROR ARM X
- 15 LH FRONT MIRROR ARM COVER / *CRA*
- 16 RH FRONT MIRROR ARM X
- 17 RH FRONT MIRROR ARM COVER X *nn*
- 18 LH FRONT CORNER PANEL GARNISH X
- 19 RH FRONT CORNER PANEL GARNISH ?
- 20 FRONT CABIN MOUNTING X
- 21 FRONT CABIN MOUNTING SHAFT X *nn*
- 22 AIR CON BLOWER MOTOR X
- 23 AIR CON COOLING COIL X
- 24 AIR CON PRESSURE PIPE (CHARGE) / *RT*
- 25 AIR CON PRESSURE PIPE (DISCHARGE) / *RT*

QTY	UNTIL PRICE	AMOUNT
1	\$845.30	\$845.30
1	\$602.40	\$602.40
1	\$394.80	\$394.80
1	\$54.60	\$54.60
1	\$656.10	\$656.10
1	\$56.20	\$56.20
1	\$580.60	\$580.60
1	\$658.40	\$658.40
1	\$95.10	\$95.10
1	\$112.30	\$112.30
1	\$658.40	\$658.40
1	\$95.10	\$95.10
1	\$112.30	\$112.30
1	\$359.60	\$359.60
1	\$126.40	\$126.40
1	\$359.60	\$359.60
1	\$126.40	\$126.40
1	\$298.60	\$298.60
1	\$298.60	\$298.60
2	\$280.60	\$561.20
1	\$1,875.20	\$1,875.20
1	\$986.20	\$986.20
1	\$1,310.30	\$1,310.30
1	\$388.10	\$388.10
1	\$316.20	\$316.20

TOTAL :
LESS 10% :
TOTAL :

\$11,647.40	\$11,928.00
\$1,164.74	\$1,192.80
\$10,482.66	\$10,735.20

S/NETT ITEMS

1 FRONT GRILLE CLIPS	1	\$80.00	\$80.00
2 FRONT MIRROR COVER CLIPS	2	\$30.00	\$60.00
3 FRONT CORNER PANEL GARNISH	1	\$30.00	\$60.00
4 AIR CON GAS	1	\$100.00	\$100.00
5 FRONT NUMBER PLATE	1	\$35.00	\$35.00

TOTAL :

\$275.00 \$335.00

TOTAL SPARE PARTS :

\$10,757.66 \$11,070.20

LABOUR DESCRIPTION

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 TO RUST PROOF / TUFF COAT ON FRONT ACCIDENT AREAS
- 4 LABOUR FOR REMOVE & REFIX FRONT DASHBOARD
- 5 WIRING CHECK
- 6 LABOUR FOR REMOVE & RENEW AIR CON COOLING COIL / BLOWER MOTOR
VACCUM AND TOP UP GAS
- 7 LABOUR FOR REPAIR & STRAIGHTEN BOTH FRONT CHASSIS FRAME

AMOUNT

\$1,400.00 *400*
 \$1,000.00 *500*
 \$300.00 *X*
 \$400.00 *X*
 \$120.00 *30*
 \$500.00 *X*
 \$500.00 *X*

TOTAL LABOUR :

\$4,220.00

TOTAL PARTS AND LABOUR :

\$15,290.20

4 Days.
 4/5
 After repair photos.
 Guna Rinal
 17/12/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items, must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: