

SMID9529H 2018 July
Volkswagen Golf 1395cc

TPA x A.
Veron.

WVWZZZAUZJW047542

Rear Bumper	Deformed	1112	✓
Rear Bumper Clips.	pc	30(SW).	✓
Rear Bumper Side Holder LH.	2nd	44	✓
Rear Bumper Reflector LH.	Wt	78	✓
Rear Bumper Reinforcement.	Dented	545	✓
Rear Bumper Centre Guide.	crushed	195	✓
Rear Bumper Lower Garnish.	Wt	325	✓
Rear Bumper Lower Garnish Chrome Moulding.	pc	145	✓
Reverse Sensor x 22	1 piece by d	$228 \times 2 = 456$	228
Reverse Sensor Holder x 04.	pc	$25 \times 4 = 100$	✓
Rear End Panel	Dented	753	✓
Rear End Panel Top Garnish	MP pc	167	X
Rear End Panel Sealant.	pc	60(SW)	✓
Taillamp LH	Crushed	368	✓
Taillamp Panel LH.	Repair	308	X

SM D9529H.

Tailgate	Dented	1634.	✓
Tailgate Lock	new	188	✗
Tailgate Weathershipe.	wt	225.	✓
Tailgate Reflector LH.	wt	342.	✓
Tailgate Lower Trim Board	Del'd	305	✓
Tailgate Lower Trim Board clips.	re	30(SN)	✓
Tailgate Glass	Shattered	1124.	✓
Tailgate Glass Molding.	2	184	✓
Tailgate Glass Sealant.	NOC	60(SN)	✓
Tailgate Glass Solar Film.		280(SN) 200(SN)	
Volkswagen Logo	2	130	✓
Golf Molding.	new	88	
Rear LH Fender	Distorted	985.	✓
Rear LH Fender Air Vent.	Del'd	48.	✓

SMD 9529H.

Rear LH Fender Inner Shield	torn	185	✓
Rear LH Fender Inner Shield clips.	✓	30(SN)	✓
Rear RH Fender Lower Trim	✓	385	X
Rear RH Fender Lower Trim clips	✓	30(SN)	X
Rear LH Fender Lower Trim Cover Upper	cracked	325	✓
Rear LH Fender Lower Trim Cover Upper clips.	✓	20(SN)	✓
Rear LH Wheel Rim.	Not Me	1048	X
Rear LH Tyre.		256(SN)	X

2283

S.N: 430

9368

853120

SMD 9529H.

Panel Beating

Spray Painting

Wiring.

To remove reverse sensor

To remove rear camera.

To remove upholstery

To transfer tailgate fittings.

To remove tailgate g/s

To vacuum and clean up glass fragments.

To spray tuff coat. 2690

~~1400~~ 1200

~~1400~~ 1000

~~50~~ 30

~~100~~ 50

~~100~~ 50

~~150~~ 60

~~150~~ 60

~~180~~ 120

60

~~120~~

~~150~~ 60

3800

16,402.00

total: 11651.20

L/S: 9.3K.

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9.3K

10 days