

Thevan

ARC

SURVEYORS & ADJUSTERS

VEHICLE NO : SMH 8927C

POLICY NO :

CLAIM NO :

OUR REF :

ARC/2022-006

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	QTY	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
		<u>PARTS</u>			
1	1	Rear bumper	Damaged	1655.00	1,324.00
2	1	Rear bumper bracket	Necessary	188.00	150.40
3	1	Rear bumper reflector right	Damaged	396.00	316.80
4	1	Rear reinforcement bar	Impacted	789.00	631.20
5	1	Rear end panel	Impacted	755.00	604.00
6	1	Rear fender	Damaged	998.00	798.40
7	1	Rear right tail lamp	Broken	858.00	686.40
8	1	Rear right boot lamp	Broken	669.00	535.20

6,308.00 less 20% 5,046.40

TOTAL PARTS:

5,046.40

1298.4

57 days



SURVEYORS & ADJUSTERS

VEHICLE NO : SMH 8927C POLICY NO :
CLAIM NO : OUR REF : ARC/2022-006

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1	<u>LABOUR</u> To fix & dismantle & remove damaged rear portions; affected damaged portion		1,000.00	1,000.00
2	To apply anti rust coat and affected areas		180.00	180.00
3	To check wiring		120.00	120.00
4	Welding and cutting of affected panles Including chasis alignment		800.00	800.00
5	Spray painting for rear portions affected parts		800.00	800.00
6	Refocusing of the front headlamp	-	-	-
7	Diagnose ECU system and reset error code	-	-	-
8	3D Wheel Alignment	-	-	-
9	To apply waterproofing sealer on end panels		120.00	120.00

Labour Total : 3,020.00 3,020.00

TOTAL (PARTS & LABOUR): 8,066.40

NETT TOTAL : 8,066.40

AGREED AT LUMP SUM : 6,900.00

45:2050

RD: 5

2578.4

2062.7

2050//

600

400 + 200

30 + 20
50

30

XNN

400 + 200
600

30 / NNN

2188.4

1750.72

71750