

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

YAP LEE MOTOR

NO 1 KAKI BUKIT AVENUE 6 #01-26

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 1555

TP Budget Direct.
Denise.

Date: 31/03/2022

Vehicle No: GBJ7082R

Make/Model: Toyota Hiace

Chasis Number: JTFHT02P000249314

ESTIMATE COST OF REPAIRS

Qty	Descriptions List Item	Amount
1	Head Lamp LH <i>cracked.</i>	\$ 760.80 ✓
1	Front Bumper <i>Rehd</i>	\$ 584.40
1	Front Bumper Side Grille LH <i>new</i>	\$ 81.10 +
1	Front Bumper Retainer LH <i>new</i>	\$ 121.10 ✓
1	Front Bumper Side Bracket LH <i>new</i>	\$ 49.00 +
1	Front Bumper Top Bracket <i>new</i>	\$ 126.50 +
1	Front Door LH <i>Ryir</i>	\$ 1,695.80 +
1	Front Door Checker LH <i>new</i>	\$ 86.50 +
2 pcs	Front Door Hinge <i>new</i>	\$ 191.00 +
1	Front Door Lock LH <i>new</i>	\$ 321.00 +
1	Front Door Pillar LH <i>Ryir</i>	\$ 855.50 +
1	Front Step Garnish LH <i>cut</i>	\$ 165.70 ✓
1	Front Step Panel LH <i>Ryir</i>	\$ 145.20 +
		\$ 5,183.60
Less 25%		\$ 1,295.90
		\$ 3,887.70
Special Nett Item		
1	Front Bumper Clip (Set) <i>new</i>	\$ 60.00 30
1	Front Door Lettering <i>new</i>	\$ 50.00 30
1	Front Bumper Side Skirt LH <i>Rehd</i>	\$ 350.00 280
		\$ 460.00
Labour cost		
1	To do computerized wheel alignment	\$ 120.00 x
2	To Transfer Front Door Mechanism	\$ 120.00 x
3	To apply undercoating	\$ 100.00 50
4	To Panel Beating, Remove & refit parts	\$ 900.00 400
5	To Spray Painting	\$ 800.00 550
		\$ 2,040.00
GRAND TOTAL		\$6,387.70

total: 2564
H/S: 2050

Adrian Lj
h/s 31/03/22.
03 Days.