



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22002469/Aty3h2 Date: 02/06/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 7372P	Veh. Inspected	GBJ 7082R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014260/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	16/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFHT02P000249314	Colour	WHITE	
Odometer	105614 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2022	Inspection Date	31/03/2022	
Survey held at	YAP LEE MOTOR BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		